

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010436/UNY3Q2**Date:** 15/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00068942202

**Claimant Vehicle
No :** SJL7561U**Insured
Vehicle No :** SJP9527K

Date of Loss: 19/10/2022

Nature of Claim: TP

Claim
No: SNM22D207497/C02/KHONGLHDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJL7561U**

Make & Model: HONDA JAZZ, 1.4 (A)

Engine No: L13A55001379

Reg. Date: 11/12/2008 (Man. Year: 2008)

Chassis No: JHMGD18508S217952

Colour: Yellow

Odometer: 209483 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Toyo 6 mm

Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,606.96	5,922.88	1,684.08	22.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,210.00	3,200.00	1,010.00	23.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,816.96	9,122.88	2,694.08	22.80
Approved Total (Overridden) (S\$)		7,300.00		
(S\$)	11,816.96	7,300.00	4,516.96	38.22
+ GST 7.00/7.00% (S\$)	827.19	511.00	316.19	38.22
Nett Amount (S\$)	12,644.15	7,811.00	4,833.15	38.22

INSPECTION

Date of Assignment: 20/10/2022

Date Inspected: 25/10/2022 Inspected At:

SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2022)
Parts:	144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL7561U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR WINDSCREEN MOULDING	Necessary	116.00 FL	*116.00 FL
2	1		*REAR GATE	Badly Dented	925.00 FL	*925.00 FL
3	1		*REAR GATE LOGO	Necessary	60.00 FL	*35.00 FL
4	1		*REAR GATE JAZZ PLATE	Necessary	75.00 FL	*38.00 FL
5	1		*REAR GATE LOCK	Dented / Jammed	145.00 FL	*145.00 FL
6	1		*REAR GATE INNER RUBBER	Twisted	195.00 FL	*195.00 FL
7	1		*REAR GATE OUTER GARNISH	Cracked	185.00 FL	*185.00 FL
8	1		*REAR GATE INNER TRIMBOARD	Not Necessary	215.00 FL	*- FL
9	10		*INNER TRIM BOARD CLIPS	Not Necessary	79.00 FL	*- FL
10	1		*REAR BUMPER	Distorted	550.00 FL	*550.00 FL
11	2		*REAR BUMPER RETAINER	Bent	56.00 FL	*56.00 FL
12	1		*SET REAR BUMPER CLIPS	Necessary	59.00 FL	*35.00 FL
13	2		*TAIL LAMP	Cracked	590.00 FL	*590.00 FL
14	1		*REAR END PANEL	Badly Dented	350.00 FL	*296.60 FL
15	1		*REAR END PANEL TOP TRIM	Twisted	85.00 FL	*85.00 FL
16	1		*REAR SPARE TYRE FLOOR PANEL	Repair	810.00 FL	*- FL
17	1		*SPARE TYRE BOARD COVER	Warped	245.00 FL	*245.00 FL
18	1		*REAR EXHAUST BOX	Repair	435.00 FL	*- FL
19	1		*FRT GRILLE	Cracked	195.00 FL	*195.00 FL
20	1		*GRILLE LOGO	Scratched	48.00 FL	*48.00 FL
21	1		*FRT BUMPER	Torn	585.00 FL	*585.00 FL
22	10		*FRT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
23	2		*FRT BUMPER RETAINER	Bent	76.00 FL	*76.00 FL
24	1		*FRT BUMPER TOW COVER	Deformed	35.00 FL	*35.00 FL
25	1		*FRT BUMPER REINFORCEMENT	Bent	335.00 FL	*185.80 FL
26	1		*FRT BUMPER LOWER GRILLE	Torn	165.00 FL	*165.00 FL
27	2		*HEADLAMP	Cracked	1,180.00 FL	*1,180.00 FL
28	2		*HEADLAMP LOWER BRACKET	Not Necessary	90.00 FL	*- FL
29	1		*AIRCON CONDENSER	Bent	655.00 FL	*655.00 FL
30	1		*FRT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
31	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS
32	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS
33	1		*REAR GATE SEALANT	Not Necessary	40.00 FS	*- FS
34	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*40.00 FS
35	1		*REAR FLOOR PANEL SEALANT	Not Necessary	40.00 FS	*- FS
36	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
37	2		*REAR FENDER INNER TRIM BOARD	Deformed / Torn	277.20 FL	*277.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,381.20	7,313.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,774.24	1,390.72
Total Parts (\$)	7,606.96	5,922.88

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	40.00	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
4	REMOVE & REFIX REAR SENSOR	New	50.00	50.00
5	REMOVE & REFIX REAR BOOT UPHOLSTERY	New	100.00	60.00
6	TRANSFER REAR GATE COMPONENTS	New	100.00	80.00
7	CAVITY PROTECTION ON AFFECTED AREAS	New	100.00	60.00
8	REMOVE & REFIX REAR EXHAUST BOX	New	100.00	0.00
9	LABOUR CHARGE (FRT)	New	600.00	400.00
10	SPRAY PAINTING (FRT)	New	600.00	500.00
11	LABOUR CHARGE (REAR)	New	1,200.00	900.00
12	SPRAY PAINTING (REAR)	New	1,100.00	900.00
Gross Labour Cost (\$\$)			4,210.00	3,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >