



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 1611A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	CORNER PANEL (O/S)	DENTED	323.70	285.00
1	HEADLAMP (O/S)	CRACKED	932.40	932.40
1	FRONT BUMPER	DISTORTED	721.90	721.90
1	STEP GARNISH (O/S)	GRAZED	302.80	302.80
1	SIGNAL LAMP (O/S)	SCRATCHED	47.00	47.00
1	TRUCK DOOR DECAL (O/S)	NECESSARY	25.00	25.00
	LESS 25% DISCOUNT		-	-578.53
			2,352.80	1,735.57
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
			80.00	-
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING SYSTEM.		60.00	20.00
	TO PUTTY AND RESPRAY ON FRONT BUMPER AND AFFECTED AREA .		1,000.00	500.00
	TO PANEL BEAT ON CAR DOOR .		1,000.00	500.00
	TO CARRY OUT BODY CRAVITY PRESERVATION.	NOT NECESSARY	200.00	-
			2,260.00	1,020.00
	<b>GRAND TOTAL</b>		<b>4,692.80</b>	<b>2,755.57</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,200.00</b>

Report Ref No. CS/SMO22010439/Uny3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.