

ASS. REC. BY:

REF: C12 / 22010443 / kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hwa Sen

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: PNF5793P Yr Regn: 06, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Keize C.C. 1198

Colour: M. D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 30982 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: A202A. 0006096

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/RIm / STD A/RIm or

Tyre Size: F: 195/65R16

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal: 8 mm

L/Bal: 8 mm

D.O.A. 17/10/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>12/1</u>	<u>5854.25 Cash</u>

Date/Time, File Pass to? : Prell. Report : Final Report

Date/Time, File Return to? _____

Days Of Repair: _____ Resurvey No. of Trip: _____

- Add Fee: : Site Insp (\$)
- : Interview (\$)
- : Tech Invs (\$)
- : Weekend (\$)

Survey Fee:	
Transportation	
S - RS	\$
Fuel	
Others	
TOTAL	

Report Format : _____ Lump Sum / I.B.I: (\$)

HWA SENG SPRAY PAINTING PTE LD

160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722

(COMPANY REGISTRATION NO.: 202017045G)

TEL : 64533100

FAX : 62669932

Date of Accident: 17/10/2022

Your Insured

Vehicle No.: GBE 911X

Not Authorized
 Anthony Bepasm

85854.25

4 days

ESTIMATE REPAIR COSTS TO TOYOTA RAIZE REG. NO. : SNF 5793 P

		S\$
1pc	O/S Headlamp <i>3160</i>	<i>Wt</i> 3579.80 ✓
1pc	O/S/F Fender	<i>Bu</i> 691.70 ✓
1pc	O/S/F Fender Garnish	<i>Ori</i> 105.70 ✓
1pc	O/S/F Fender Inner Shield	<i>Pa</i> 281.50 X
1pc	Front Bumper <i>1020</i>	<i>Wt</i> 1148.50 ✓
1pc	Front Bumper Right Retainer	<i>Ori</i> 67.90 ✓
1pc	Front Bumper Right Fog Lamp Cover	<i>Mit</i> 129.30 ✓
1pc	Front Bumper Grille	<i>Wt</i> 422.60 ✓
1pc	Front Bumper Outer Moulding	<i>Pa</i> 237.80 X
1pc	Front Bumper Right Sensor	<i>Mit</i> 340.10 ✓
1pc	Bonnet	<i>R</i> 1294.10 X
1pc	Front Bumper Reinforcement	<i>R</i> 855.00 X
1pc	Front Bumper Lower Spoiler	<i>Ori</i> 436.30 ✓

		9590.30
Less : 25%		2397.58

		7192.72

LABOUR & MISC CHARGES

Panel Knocking	750.00	<i>450</i>
Spray Painting	800.00	<i>600</i>
Wire Checking	80.00	<i>20</i>

TOTAL

8822.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

HWA SENG SPRAY PAINTING PTE LTD

