

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010444/GCM4**Date:** 27/02/2023**REFERENCE**

Insured/Claimant: KEK SIOW YEN ESTHER Policy No: 2100492658
Date of Loss: 15/10/2022 Nature of Claim: OD Claim No: 9761021975SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ2274T**
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZD250776
Reg. Date: 30/11/2016 (Man. Year: 2016) Chassis No: WAUZZZ8U1HR022697
Colour: White Odometer: 144629 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$87,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R17 Rear Tyre Size: 235/55 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,765.00	776.00	13,989.00	94.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,852.00	2,652.00	3,200.00	54.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,617.00	3,428.00	17,189.00	83.37
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	20,217.00	3,028.00	17,189.00	85.02
+ GST 8.00/8.00% (S\$)	1,617.36	242.24	1,375.12	85.02
Nett Amount (S\$)	21,834.36	3,270.24	18,564.12	85.02

INSPECTION

Date of Assignment: 24/10/2022
Date Inspected: 20/10/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,376.00 FS	*- FS
2	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	171.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	196.00 FS	*- FS
4	1		*FRONT BUMPER SPOILER	Cut	426.00 FS	*340.80 FS
5	1		*FRONT FENDER - LH	Repair	1,014.00 FS	*- FS
6	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	73.00 FS	*- FS
7	1		*FRONT FENDER BRACE - LH	Not Necessary	116.00 FS	*- FS
8	1		*FRONT FENDER BRACKET - LH	Not Necessary	92.00 FS	*- FS
9	7		*FRONT FENDER RIVET	Not Necessary	27.00 FS	*- FS
10	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	260.00 FS	*- FS
11	1		*FRONT WHEEL SPOILER - LH	Not Necessary	82.00 FS	*- FS
12	1		*HEADLIGHT MOUNTING - LH	Not Necessary	132.00 FS	*- FS
13	1		*HEADLIGHT RETAINING PLATE - LH	Not Necessary	97.00 FS	*- FS
14	1		*HEADLIGHT - LH	Not Necessary	8,294.00 FS	*- FS
15	1		*LIFT CYLINDER - LH	Not Necessary	231.00 FS	*- FS
16	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
17	2		*FRONT WHEEL COVER - LH / RH	Necessary	544.00 FS	*435.20 FS
18	1		*RADIATOR AIR GUIDE - LH	Not Necessary	30.00 FS	*- FS
19	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **14,765.00** **776.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,852.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >