

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22010446/GNCE2**Date:** 28/03/2023REFERENCE

Insured/Claimant:	FENG LIYUAN	Policy No:	
Date of Loss:	16/10/2022	Nature of Claim:	OD Claim No: 0297689777SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF8122G	Engine No:	DGK005631
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Chassis No:	WAUZZZF6M2089465
Reg. Date:	23/06/2022 (Man. Year: 2021)	Odometer:	3230 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$288,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,071.00	2,854.00	14,217.00	83.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,472.00	2,122.00	4,350.00	67.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,543.00	4,976.00	18,567.00	78.86
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	22,543.00	3,976.00	18,567.00	82.36
+ GST 8.00/8.00% (S\$)	1,803.44	318.08	1,485.36	82.36
Nett Amount (S\$)	24,346.44	4,294.08	20,052.36	82.36

INSPECTION

Date of Assignment:	24/10/2022		
Date Inspected:	20/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,705.00 FS	*1,160.80 FS
2	1		*FRONT BUMPER SECURING STRIP -LH	Not Necessary	42.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT -LH	Not Necessary	126.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	298.00 FS	*- FS
5	2		*FRONT PARKING AID SENSOR SUPPORT -LH/RH	Not Necessary	66.00 FS	*- FS
6	1		*FRONT BUMPER UNDERRUN BAR -CENTER	Not Necessary	968.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER -LH	Deformed	252.00 FS	*201.20 FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	471.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Cut	267.00 FS	*213.20 FS
10	1		*FRONT PARKING AID SENSOR SUPPORT -LH	Not Necessary	38.00 FS	*- FS
11	1		*FRONT BUMPER TRIM -LH	Not Necessary	179.00 FS	*- FS
12	2		*FRONT PARKING AID SENSOR -INNER /OUTER	Not Necessary	531.00 FS	*- FS
13	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
14	1		*HORN LOW TONE -LH	Not Necessary	208.00 FS	*- FS
15	1		*FRONT FENDER -LH	Not Necessary	1,462.00 FS	*- FS
16	1		*FRONT FENDER BRACE -LH	Not Necessary	250.00 FS	*- FS
17	1		*FRONT WHEEL HOUSING LINER -LH	Not Necessary	286.00 FS	*- FS
18	1		*FRONT WHEEL SPOILER -LH	Damaged	181.00 FS	*144.40 FS
19	2		*FRONT WHEEL COVER -LH/RH	Necessary	1,418.00 FS	*1,134.40 FS
20	1		*HEADLIGHT MOUNTING -LH	Not Necessary	132.00 FS	*- FS
21	1		*HEADLIGHT -LH	Not Necessary	7,440.00 FS	*- FS
22	1		*LIFT CYLINDER -LH	Not Necessary	153.00 FS	*- FS
23	1		*LIFT CYLINDER HOSE	Not Necessary	145.00 FS	*- FS
24	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	43.00 FS	*- FS
25	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	17,071.00 2,854.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER ,LHS FRONT BUMPER LOWER SPOILER ,LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,000.00	950.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,472.00	2,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >