



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9103Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEAD LAMP RH	CRACKED	1,640.30	1,245.90
1	FRONT HEAD LAMP LOWER BRACKET	SERVICEABLE	124.00	-
1	FRONT GRILLE	SERVICEABLE	568.10	-
1	FRONT GRILLE CHROME MOULDING	SERVICEABLE	235.00	-
1	FRONT BUMPER	BUCKLED	687.50	545.00
1	FRONT BUMPER DUST COVER	CRACKED	239.10	178.20
1	FRONT BUMPER LOWER GRILLE SIDE	SERVICEABLE	287.60	-
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	89.60	89.60
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	568.40	-
1	FRONT BUMPER REINFORCEMENT SPONGE	SERVICEABLE	468.30	-
1	WINDSCREEN WASHER TANK	SERVICEABLE	365.00	-
	LESS 25% DISCOUNT		-1,318.23	-514.68
			3,954.67	1,544.02
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		800.00	200.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		500.00	220.00
	TO CHECK WIRING SYSTEM.		50.00	20.00
			1,350.00	440.00
	GRAND TOTAL		5,304.67	1,984.02
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,550.00

Report Ref No. CS/LIP22010452/Kwy3m4

MARKET VALUE: \$72,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$34,742.00=NETT VALUE: \$37,258.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.