

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI22010453/KWY3E2
Date: 21/02/2023**REFERENCE**Insured/Claimant: Safetech Engineering Pte Ltd Policy No: DMCVSNW0003422202
Date of Loss: 19/10/2022 Nature of Claim: OD Claim No: SNM22D207531/C01/TANCHC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBJ1074D**
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2836573
Reg. Date: 02/01/2019 (Man. Year: 2018) Chassis No: JTFAT35Y00K212226
Colour: Silver Odometer: 144671 km
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$74,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes**CONDITION OF TYRES**Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D)
Front Left Side: Bridgestone 2 mm Rear Left Side: Yokohama 2/2 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Yokohama 4/4 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,920.00	2,018.00	-98.00	-5.10
Miscellaneous Items	25.00	25.00	0.00	0.00
Labour	747.60	747.60	0.00	0.00
Paintwork Labour	446.18	446.18	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,138.78	3,236.78	-98.00	-3.12
- Excess (S\$)	350.00	350.00	0.00	0.00
(S\$)	2,788.78	2,886.78	-98.00	-3.51
+ GST 7.00/8.00% (S\$)	195.21	230.94	-35.73	-18.30
Nett Amount (S\$)	2,983.99	3,117.72	-133.73	-4.48

INSPECTIONDate of Assignment: 21/10/2022 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 10/11/2022 Inspected At: 160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 5.0 days**Adjuster:** KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Feb 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ1074D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*Spare Parts		1,920.00 F	*1,920.00 F	
2	1		*WINDSCREEN SEAL	Necessary	-	*95.00 F	
3	1		*FRT PANEL CLIP	Necessary	-	*3.00 F	
					Total Parts (\$)	1,920.00	2,018.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Extra	25.00	25.00
			Sub Total (\$)	25.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Including Material	New	446.18	446.18
Labour Items				
2	Total of Labour	New	747.60	747.60
			Gross Labour Cost (\$)	1,193.78

Report was unsubmitted during this print-out.

< END OF ESTIMATES >