11/23/22, 10:48 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22010460/UVY3M4

**Date:** 23/11/2022

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001962355

Claimant Vehicle SML5249A Insured Vehicle No: SMA6755G

No: SIVIL5249A Insured venicle No: SIVIA0753G

Date of Loss: 20/10/2022 Nature of Claim: TP Claim No: 288124

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SML5249A

 Make & Model:
 MERCEDES-BENZ A200, 1.3 AMG LINE (A)
 Engine No:
 28291480086369

 Reg. Date:
 24/05/2019 (Man. Year: 2019)
 Chassis No:
 WDD1770872J075091

Colour: White Odometer: 43017 km

Engine Capacity: 1332 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm
Front Right Side: Goodyear 7 mm
Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,837.80	2,391.03	8,446.77	77.94
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,040.00	1,010.00	3,030.00	75.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	14,877.80	3,401.03	11,476.77	77.14
	Approved Total (Overridden) (S\$)		2,700.00		
	Nett Amount (S\$)	14,877.80	2,700.00	12,177.80	81.85

**INSPECTION** 

Date of Assignment: 21/10/2022

Date Inspected: 21/10/2022 Inspected At: 130 Bedok Reservoir Road, #08-1339

Eunos Spring, Singapore 470130

Zoom Autowerks Pte Ltd (Bedok)

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2022)

Parts: 144 MERCEDES-BENZ A200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SML5249A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	112.00 FL	*- FL
2	1		*REAR TAILGATE	Not Necessary	2,200.00 FL	*- FL
3	1		*REAR TAILGATE RUBBER	Not Necessary	185.00 FL	*- FL
4	1		*REAR TAILGATE LOGO	Not Necessary	78.00 FL	*- FL
5	1		*REAR TAILGATE A200 EMBLEM	Not Necessary	78.00 FL	*- FL
6	1		*REAR END PANEL	Repair	1,248.00 FL	*- FL
7	1		*REAR END PANEL INNER GARNISH	Not Necessary	165.00 FL	*- FL
8	1		*REAR BUMPER }	Dented / Torn	2,085.00 FL	*1,337.00 FL
9	1		*REAR BUMPER TOW HOOK COVER }		28.00 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	817.00 FL	*465.00 FL
11	1		*REAR BUMPER REFLECTORS (2Pcs)	O/s Cracked	336.00 FL	*62.00 FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	170.00 FL	*- FL
13	1		*REAR BUMPER LOWER DIFFUSER	Deformed	1,280.00 FL	*322.45 FL
14	1		*REAR BUMPER PDC SENSORS (2Pcs)	O/s Shorted	770.00 FL	*192.00 FL
15	2		*REAR BUMPER SIDE SENSORS	Not Necessary	770.00 FL	*- FL
16	1		*REAR BUMPER CENTRE CHROME MOULDING	Scratched	325.00 FL	*278.25 FL
17	2		*REAR BUMPER SIDE CHROME MOULDINGS	Not fitted	392.00 FL	*- FL
18	1		*REAR EXHAUST CHROME TAIL PIPE	Not Necessary	285.00 FL	*- FL
19	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc.	=		
				Sub Total (S\$)	11,404.00	2,656.70
	- List Item Discount on L Items 5.00/10.00% (S\$)				566.20	265.67
				Total Parts (S\$)	10,837.80	2,391.03

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	180.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	0.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO APPLY UNDERCOATING	New	200.00	0.00
7	PANEL BEATING	New	1,600.00	480.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	400.00
	Gross Labou	4,040.00	1,010.00	
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >