

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 1847H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT	TO REPAIR SEE LABOUR	1,971.80	-
1	REAR BUMPER	DENTED	912.75	912.75
1	REAR BUMPER LWR	CUT	932.96	932.96
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	529.68	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	32.40	-
1	REAR TAILLAMP RH	NOT NECESSARY	1,515.35	-
1	REAR BUMPER REFLECTOR LENS RH	BROKEN	43.73	43.73
	LESS 10% DISCOUNT		-593.87	-188.95
			5,344.80	1,700.49
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
			40.00	30.00
	<u>LABOUR</u>			
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.	NOT NECESSARY	180.00	-
	REMOVE & REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS.		120.00	30.00
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT.		1,600.00	800.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		1,400.00	900.00
	·		3,420.00	1,730.00
	GRAND TOTAL		8,804.80	3,460.49

Report Ref No. CS/SMR22010463/Eqy3m4



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			3,460.49
-----------------------------	--	--	----------

Report Ref No. CS/SMR22010463/Eqy3m4



Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator