

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010464/ENY3Q2**Date:** 30/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00105772200
Claimant Vehicle No :	SNG2082Y	Insured Vehicle No :	SNF349Y
Date of Loss:	01/10/2022	Nature of Claim: TP	Claim No: SNM22D207075/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG2082Y		
Make & Model:	AUDI A1, 999cc SB 1.0 TFSI (PI) (A)	Engine No:	CHZ399351
Reg. Date:	08/08/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V9J1003473
Colour:	White	Odometer:	56275 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,370.00	11,854.90	4,515.10	27.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,042.00	12,622.00	6,420.00	33.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,412.00	24,476.90	10,935.10	30.88
+ GST 8.00/8.00% (S\$)	2,832.96	1,958.15	874.81	30.88
Nett Amount (S\$)	38,244.96	26,435.05	11,809.91	30.88

INSPECTION

Date of Assignment:	21/10/2022	
Date Inspected:	13/10/2022	Inspected At: BENOI (PREMIUM) Repairer: Premium Automobiles Pte Ltd (UBI)
Estimated Period of Repair:	11.0 days	

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2023)
Parts:	144	AUDI A1 999cc SB 1.0 TFSI (PI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG2082Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SIDE PANEL -LH	Dented	4,445.00 FS	*4,445.00 FS
2	1		*REAR WINDOW	Necessary	905.00 FS	*905.00 FS
3	1		*REAR SIDE WINDOW -LH	Necessary	635.00 FS	*635.00 FS
4	2		*WINDOW PRIMER	Necessary	44.00 FS	*43.40 FS
5	1		*REAR WHEEL HOUSING LINER	Not Necessary	260.00 FS	*- FS
6	1		*REAR WHEEL SPOILER -LH	Not Necessary	39.00 FS	*- FS
7	1		*REAR WHEEL SPOILER COVER -LH	Not Necessary	4.00 FS	*- FS
8	1		*REAR WHEEL HOUSING ATTACHMENT PARTS -LH	Not Necessary	673.00 FS	*- FS
9	1		*REAR DOOR -LH	Dented	3,265.00 FS	*3,265.00 FS
10	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	134.00 FS	*- FS
11	1		*REAR DOOR CATCH -LH	Not Necessary	105.00 FS	*- FS
12	1		*REAR DOOR SEAL -LH INNER	Necessary	213.00 FS	*178.50 FS
13	1		*REAR WINDOW REGULATOR -LH	Not Necessary	286.00 FS	*- FS
14	1		*REAR WINDOW REGULATOR MOTOR -LH	Not Necessary	300.00 FS	*- FS
15	1		*REAR DOOR MOUNTING BAR -LH	Not Necessary	182.00 FS	*- FS
16	1		*REAR DOOR BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
17	1		*REAR DOOR BOWDEN CABLE HOLDER	Not Necessary	4.00 FS	*- FS
18	1		*REAR DOOR INNER PANEL -LH	Not Necessary	1,831.00 FS	*- FS
19	1		*REAR ALUMINIUM RIM -LH	Cut	1,303.00 FS	*1,303.00 FS
20	1		*REAR ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
21	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
22	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
23	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
24	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
25	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
27	1		*SUNDRIES	Not Necessary	600.00 FS	*- FS
Total Parts (\$\$)					16,370.00	11,854.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID	New	280.00	0.00
2	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE RENEWAL OF LHS REAR FENDER	New	600.00	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	400.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	200.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT ,BACK REST ,HAT TRAY ,CD PILLAR TRIMS ,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
7	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	350.00	350.00
8	TO DISMANTLE AND REINSTALL REAR BUMPER .TO RENEW LHS REAR DOOR .TO CUT OUT AND WELD LHS REAR FENDER AND LHS OUTER WHEEL HOUSING RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	7,700.00	4,550.00
9	TO RESPRAY REAR BUMPER ,LHS REAR FENDER ,LHS REAR DOOR ,DOOR HANDLE ,ROOF CHANNEL ,LHS SILL PANEL,DRAIN CHANNEL ,DOOR ENTRANCES AND REAR END PANELLING	New	6,000.00	3,250.00
10	TO RENEW LHS REAR RIM ,TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			19,042.00	12,622.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >