

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010465/TQY3Q2**Date:** 11/04/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00252832101

Claimant Vehicle No : SLH8015X**Insured Vehicle No :** SMU5607C

Date of Loss: 19/10/2022

Nature of Claim: TP

Claim No: SNM22D207509/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLH8015X**

Make & Model: TOYOTA PRIUS, 1.5 (A)

Engine No: 2ZRR937872

Reg. Date: 18/11/2016 (Man. Year: 2016)

Chassis No: ZVW506050552

Colour: Black

Odometer: 595305 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,989.00	9,525.80	3,463.20	26.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,380.00	7,040.00	3,340.00	32.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,369.00	16,565.80	6,803.20	29.11
+ GST 8.00/8.00% (S\$)	1,869.52	1,325.26	544.26	29.11
Nett Amount (S\$)	25,238.52	17,891.06	7,347.46	29.11

INSPECTION

Date of Assignment: 21/10/2022

Date Inspected: 21/10/2022

Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)
Parts: 144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLH8015X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*REAR REGN PLATE	Bent	80.00 FS	*80.00 FS
3	1		*PHV STICKER	Necessary	20.80 FS	*20.80 FS
4	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
5	1		*COVER ,RR BUMPER	Deformed	478.90 FS	*478.90 FS
6	1		*REINFORCEMENT	Bent	360.10 FS	*360.10 FS
7	1		*SEAL ,RR BUMPER	Necessary	95.50 FS	*95.50 FS
8	1		*SEAL ,RR BUMPER	Necessary	95.50 FS	*95.50 FS
9	1		*GUARD ,RR BUMPER	Deformed	623.50 FS	*623.50 FS
10	1		*FILLER ,RR BUMPER	Not Necessary	133.60 FS	*- FS
11	1		*FILLER ,RR BUMPER	Deformed	133.60 FS	*133.60 FS
12	10		*PIECE ,RR BUMPER	Necessary	48.00 FS	*45.00 FS
13	1		*PANEL SUB-ASSY ,BODY	Bent	707.10 FS	*707.10 FS
14	1		*COVER ,FLOOR UNDER	Not Necessary	189.20 FS	*- FS
15	1		*COVER ,RR BODY	Not Necessary	249.10 FS	*- FS
16	1		*COVER ,FLOOR UNDER	Not Necessary	261.60 FS	*- FS
17	1		*PANEL SUB ASSY ,BACK	Bent	1,238.40 FS	*1,238.40 FS
18	1		*WEATHERSTRIP ,BACK	Twisted	402.50 FS	*402.50 FS
19	1		*GLASS SUB-ASSY ,BACK	Necessary	1,565.90 FS	*1,565.90 FS
20	1		*GLASS SUB-ASSY ,BACK	Broken	821.20 FS	*821.20 FS
21	1		*STAY ASSY ,BACK	Not Necessary	262.20 FS	*- FS
22	1		*STAY ASSY ,BACK	Not Necessary	262.20 FS	*- FS
23	1		*LOCK ASSY ,BACK DOOR	Not Necessary	505.50 FS	*- FS
24	1		*COVER ,BACK DOOR	Not Necessary	32.70 FS	*- FS
25	1		*STRIKER ASSY,BACK	Not Necessary	28.00 FS	*- FS
26	1		*GARNISH SUB-ASSY	Cracked	1,004.70 FS	*1,004.70 FS
27	1		*PLATE ,LUGGAGE COMPT	Necessary	59.10 FS	*59.10 FS
28	1		*EMBLEM SUB-ASSY	Necessary	77.40 FS	*77.40 FS
29	1		*PLATE ,LUGGAGE COMPT	Necessary	62.20 FS	*62.20 FS
30	1		*LENS & BODY ,RR	Not Necessary	489.00 FS	*- FS
31	1		*LENS & BODY ,RR	Cracked	489.00 FS	*479.60 FS
32	1		*COVER ,RR	Not Necessary	69.90 FS	*- FS
33	1		*COVER ,RR	Not Necessary	69.90 FS	*- FS
34	1		*LENS & BODY ,RR	Not Necessary	519.70 FS	*- FS
35	1		*LENS & BODY ,RR	Cut	519.70 FS	*519.70 FS
36	1		*LAMP SUB-ASSY	Not Necessary	311.50 FS	*- FS
37	1		*COVER ,RR BUMPER	Not Necessary	16.70 FS	*- FS
38	1		*SIKA 182010 SIKA TACK GO! (BLA)	Necessary	108.00 FS	*108.00 FS
39	1		*SIKA 207 G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS
40	1		*COVER ,DECK TRIM	Deformed	52.50 FS	*52.50 FS
41	2		*GUIDE ,RR	Deformed	7.80 FS	*7.80 FS
42	1		*COVER DECK TRIM REAR	Deformed	136.80 FS	*136.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **12,989.00** **9,525.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING & CONDUCT LEAK TEST	New	180.00	180.00
2	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
3	R/I REAR LOWER & UPPER GLASS	New	720.00	720.00
4	R/I BOOT LID INTERIOR TRIMMING	New	720.00	360.00
5	CHECK & RE-ADJUST FRONT DRIVER SEAT	New	720.00	360.00
6	REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA	New	4,320.00	2,880.00
7	RESPRAY ACC AFF AREA	New	3,540.00	2,360.00
Gross Labour Cost (S\$)			10,380.00	7,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >