

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010470/KVY3Q2**Date:** 05/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00198802100

Claimant Vehicle No : SKZ5550D **Insured Vehicle No :** SDZ899P

Date of Loss: 13/10/2022 Nature of Claim: TP Claim No: SNM22D207511/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ5550D**

Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) Engine No: FB20YE43903

Reg. Date: 29/12/2018 (Man. Year: 2018) Chassis No: JF1SJ5KC5JG112280

Colour: Metallic Grey Odometer: 62148 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17

Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,692.00	1,648.80	43.20	2.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	875.00	225.00	20.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,792.00	2,523.80	268.20	9.61
Approved Total (Overridden) (\$\$)		2,000.00		
(\$\$)	2,792.00	2,000.00	792.00	28.37
+ GST 7.00/7.00% (\$\$)	195.44	140.00	55.44	28.37
Nett Amount (\$\$)	2,987.44	2,140.00	847.44	28.37

INSPECTION

Date of Assignment: 31/10/2022

Date Inspected: 28/10/2022 Inspected At: Ah Lim Motor Company (Sin Ming)
176 Sin Ming Drive #05-12, Sin Ming AutoCare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2022)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ5550D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Dented	600.00 FN	*600.00 FN
2	10		*FRONT BUMPER CLIP	Necessary	60.00 FN	*60.00 FN
3	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	22.00 FN	*22.00 FN
4	1		*FRONT FENDER LH	Bent	300.00 FN	*300.00 FN
5	8		*FENDER COWLING CLIP	Not Necessary	48.00 FN	*- FN
6	1		*FRONT ALLOY RIM LH	Dented	850.00 FN	*850.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	1,880.00	1,832.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	188.00	183.20
Total Parts (\$\$)	1,692.00	1,648.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND REFOCUS HEADLAMP	New	20.00	15.00
2	TO WHEEL ALIGNMENT	New	80.00	60.00
3	TO DISMANTLE AND REPLACE DAMAGE PARTS ,TO KNOCK ,ALIGN AND REPAIR FRONT LH AFFECTED AREA	New	500.00	400.00
4	TO SPRAY FRONT FENDER LH AND FRONT BUMPER	New	500.00	400.00
Gross Labour Cost (\$\$)			1,100.00	875.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >