

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22010472/KNY3Q2**Date:** 28/10/2022REFERENCE

|                   |                        |                  |              |               |
|-------------------|------------------------|------------------|--------------|---------------|
| Insured/Claimant: | LINER SHIPPING PTE LTD | Policy No:       | DMCG21014808 |               |
| Date of Loss:     | 20/10/2022             | Nature of Claim: | OD           | Claim No: N/A |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>YN4182L</b>                    |             |              |
| Make & Model:               | MITSUBISHI FM65FM1RDEA, 7.5 D (M) | Engine No:  | 6M60179250   |
| Reg. Date:                  | 30/08/2013 (Man. Year: 2013)      | Chassis No: | FM65FMA10040 |
| Colour:                     | White                             | Odometer:   | 280427 km    |
| Engine Capacity:            | 7545 cc                           |             |              |
| Market Value/New Car Price: | S\$18,000.00                      |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |                  |
|-------------------|---------------|------------------|------------------|
| Front Tyre Size:  | 295/80 R22.5  | Rear Tyre Size:  | 295/80 R22.5 (D) |
| Front Left Side:  | Triangle 7 mm | Rear Left Side:  | Triangle 2/2 mm  |
| Front Right Side: | Triangle 7 mm | Rear Right Side: | Triangle 2/2 mm  |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 15,456.00         | 15,175.00         | 281.00            | 1.82          |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 1,400.00          | 1,000.00          | 400.00            | 28.57         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>16,856.00</b>  | <b>16,175.00</b>  | <b>681.00</b>     | <b>4.04</b>   |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>1,179.92</b>   | <b>1,132.25</b>   | <b>47.67</b>      | <b>4.04</b>   |
| <b>Nett Amount (S\$)</b>      | <b>18,035.92</b>  | <b>17,307.25</b>  | <b>728.67</b>     | <b>4.04</b>   |

INSPECTION

Date of Assignment: 21/10/2022

Date Inspected: 21/10/2022 Inspected At:

Autoexcel Engineering Pte Ltd (HQ)  
160 Sin Ming Drive #06-01,, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

According to the repairer, owner will do own cash repair for his vehicle .

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | (Last Synchronised: 28 Oct 2022)   |  |
| <b>Parts:</b>        | N/A  | mitsubishi FM65FM1RDEA 7.5 D (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for YN4182L)   |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition     | Repairer's | Amount      |
|-----|-----|----------|--|---------------|------------|-------------|
| 1   | 1   |          | *REAR DECK CANOPY SHELTER (TOP) (WCP)        | Bent          | 6,500.00 F | *6,500.00 F |
| 2   | 4   |          | *REAR DECK MAIN STAND (WCP)                  | Bent          | 3,200.00 F | *3,200.00 F |
| 3   | 1   |          | *REAR DECK CANOPY GLASS MOULDING (50%)       | Necessary     | 253.00 FS  | *110.00 FS  |
| 4   | 1   |          | *REAR DECK CANOPY SEALANT (WCP)              | Not Necessary | 120.00 F   | *- F        |
| 5   | 1   |          | *REAR DECK CANOPY SIDE SUPPORT BEAM RH (WCP) | Bent          | 1,400.00 F | *1,400.00 F |
| 6   | 1   |          | *CABIN REAR CANOPY PANEL (WCP)               | Bent          | 2,000.00 F | *2,000.00 F |

F=Franchise part. S=SpcNett.

|  |                  |                  |
|--|------------------|------------------|
| <b>Sub Total (\$)</b>                          | <b>13,473.00</b> | <b>13,210.00</b> |
| <b>+ Margin on L,N Items 15.00/15.00% (\$)</b> | 1,983.00         | 1,965.00         |
| <b>Total Parts (\$)</b>                        | <b>15,456.00</b> | <b>15,175.00</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                      | Particulars   | Lab.Type | Repairer's | Amount   |
|-------------------------|---|----------|------------|----------|
| <u>Labour Items</u>     |   |          |            |          |
| 1                       | LABOUR CHARGES TO REMOVE REFIX ,REPLACE REAR CANOPY | New      | 1,400.00   | 1,000.00 |
| Gross Labour Cost (S\$) |   |          | 1,400.00   | 1,000.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >