

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22010477/KNY3Q2**Date:** 30/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00048592200		
<b>Claimant Vehicle No :</b>	SMG921B	<b>Insured Vehicle No :</b>	GX9023R		
Date of Loss:	12/10/2022	Nature of Claim:	TP	Claim No:	SNM22D207544/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMG921B</b>		Engine No:	27091031514350
Make & Model:	MERCEDES-BENZ GLA180, 1.6 (A)		Chassis No:	WDC1569422J465656
Reg. Date:	03/12/2018 (Man. Year: 2017)		Odometer:	72141 km
Colour:	Metallic Black		Engine Capacity:	1595 cc
Market Value/New Car Price:	N/A		Sum Insured (\$\$):	<b>Market Value/New Car Price</b>

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,119.40	3,567.51	9,551.89	72.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	1,110.00	2,050.00	64.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>16,279.40</b>	<b>4,677.51</b>	<b>11,601.89</b>	<b>71.27</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,750.00</b>		
<b>(\$\$)</b>	16,279.40	3,750.00	12,529.40	76.96
<b>+ GST 7.00/7.00% (\$\$)</b>	1,139.56	262.50	877.06	76.96
<b>Nett Amount (\$\$)</b>	<b>17,418.96</b>	<b>4,012.50</b>	<b>13,406.46</b>	<b>76.96</b>

**INSPECTION**

Date of Assignment:	21/10/2022	
Date Inspected:	14/11/2022	Inspected At: 160 Sin Ming Drive #06-09 Sin Ming Autocity
Estimated Period of Repair:	4.0 days	Repairer:MBM Wheelpower Pte Ltd (Sin Ming)

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Nov 2022)**Parts:** M1-SUV MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMG921B)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,168.00 FL	*1,907.90 FL
2	1		*TAILGATE WEATHERSTRIP	Serviceable	237.00 FL	*- FL
3	1		*TAILGATE HINGE LH	Repair	99.00 FL	*- FL
4	1		*TAILGATE HINGE RH	Repair	99.00 FL	*- FL
5	1		*TAILGATE STAY LH	Serviceable	703.00 FL	*- FL
6	1		*TAILGATE STAY RH	Serviceable	297.00 FL	*- FL
7	1		*TAILGATE LOCK	Repair	297.00 FL	*- FL
8	1		*TAILGATE REVERSE CAMERA	No such part	2,158.00 FL	*- FL
9	1		*TAILGATE LICENSE PLATE	Serviceable	103.00 FL	*- FL
10	1		*TAILGATE MERCEDES LOGO	Necessary	52.00 FL	*52.00 FL
11	1		*TAILGATE TRIM STRIP	Serviceable	148.00 FL	*- FL
12	1		*TAILGATE GLA180 EMBLEM	Necessary	91.00 FL	*91.00 FL
13	1		*TAILGATE LAMP LH	Serviceable	505.00 FL	*- FL
14	1		*TAILGATE LAMP RH	Serviceable	505.00 FL	*- FL
15	1		*REAR BUMPER	Dented / Buckled	1,228.00 FL	*1,228.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Repair	650.00 FL	*- FL
17	4		*REAR BUMPER SENSOR	Serviceable	1,000.00 FL	*- FL
18	10		*REAR BUMPER CLIP	Necessary	80.00 FL	*80.00 FL
19	1		*REAR BUMPER LOWER SPOILER	Dented	680.00 FL	*605.00 FL
20	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	75.00 FL	*- FL
21	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	75.00 FL	*- FL
22	1		*REAR BUMPER TOWING COVER	Serviceable	91.00 FL	*- FL
23	1		*REAR BUMPER BRACKET	Repair	75.00 FL	*- FL
24	1		*TAIL LAMP LH	Serviceable	760.00 FL	*- FL
25	1		*TAIL LAMP RH	Serviceable	760.00 FL	*- FL
26	1		*END PANEL	Repair	1,400.00 FL	*- FL
27	1		*END PANEL TOP GARNISH	Serviceable	130.00 FL	*- FL
28	1		*NUMBER PLATE & HOLDER	Serviceable	50.00 FS	*- FS
29	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>14,566.00</b>	<b>3,963.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,446.60	396.39
<b>Total Parts (\$)</b>	<b>13,119.40</b>	<b>3,567.51</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,400.00	500.00
2	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	150.00	20.00
3	TO REMOVE & REFIT ALL SENSOR	New	80.00	60.00
4	TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	New	250.00	0.00
5	TO APPLY ANTI RUST COATING	New	80.00	30.00
6	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	500.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >