



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/KT/6277/2820/TP/08.21
Date : 06 September 2021

To: Skyway Motor Pte Ltd
c/o 25 Kaki Bukit Road 4
#01-55, Synergy @ Kaki Bukit
Singapore 417800

VEHICLE APPRAISAL REPORT

Name of Workshop : Apex Motoring
Place of inspection : 25 Kaki Bukit Road 4 #01-55, Synergy @ Kaki Bukit, Singapore 417800
Date of Assignment : 12 August 2021
Date of Accident : 11 August 2021
Date of Inspection : 12 August 2021

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: SMV 2820S	Chassis Frame No.	: ZWR800434571
Make / Model	: Toyota Noah Hybrid 7-Seater 1.8X CVT	Engine No. (Logcard)	: 2ZR0F29361
Year of Manufacture/Reg	: 2020	Odometer Reading	: 70,644 KM
Colour	: White		
Class / Type	: MPV		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Excellent
Paintwork : Excellent
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	Davanti 195/65R15	8 mm
Front R	Davanti 195/65R15	8 mm
Rear L	Davanti 195/65R15	8 mm
Rear R	Davanti 195/65R15	8 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount	
		LIST ITEMS:-				
1	1 pc	rear bumper	grazed	\$ 808.15	repair	XR
2	1 pc	r/h rear fender	buckled	\$ 1,062.10	\$ 1,062.10	SN\$300 repair
3	1 pc	r/h rear sliding door	buckled	\$ 1,680.35	\$ 1,680.35	1594
4	1 pc	r/h rear sliding door window black tape	necessary	\$ 290.00	\$ 290.00	
5	1 pc	r/h side skirt	scratched	\$ 758.10	repair	XR
6	1 pc	rear axle	buckled	\$ 2,017.95	\$ 2,017.95	XNN
7	1 pc	r/h rear shock absorber	bent	\$ 166.20	\$ 166.20	XNN
8	1 pc	r/h rear wheel bearing	damaged	\$ 360.20	\$ 360.20	
				\$ 6,334.90	\$ 5,576.80	2244.20
		Less 25%			\$ 1,394.20	1683.15 sn 300
				\$ 6,334.90	\$ 4,182.60	
		SPECIAL NETT ITEMS:-				
9	1 tube	r/h rear fender glass silicon sealant	necessary	\$ 80.00	\$ 60.00	X NN
10	1 pc	r/h rear sports rim	distorted	\$ 380.00	\$ 380.00	
11	1 pc	r/h rear tyre @50% depreciation	scratched	\$ 280.00	\$ 140.00	XNN
				\$ 740.00	\$ 580.00	440
Sub - Total				\$ 7,074.90	\$ 4,762.60	



6 tampines st 73, #01-03, singapore 528825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m


Our Reference : KAAS/KT/6277/2820/TP/08.21
 Vehicle Number : SMV 2820S

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 7,074.90	\$ 4,762.60
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,440.00	\$ 1,320.00 700
2		To check wiring and rewire		\$ 60.00	\$ 50.00 30
3		To deactivate/ activate/ check hybrid system		\$ 300.00	\$ 250.00 150
4		To remove and reinstall rear sliding door components		\$ 180.00	\$ 150.00 60
5		To remove and reinstall r/h rear fender glass		\$ 180.00	\$ 140.00 80
6		To remove and reinstall rear undercarriage		\$ 280.00	\$ 220.00 180
7		To perform 4 wheel alignment		\$ 120.00	\$ 100.00 80
8		To apply anti-rust		\$ 120.00	\$ 80.00 40
9		To putty and spray-paint of affected areas		\$ 1,560.00	\$ 1,440.00 800
				\$ 4,240.00	\$ 3,750.00 2120
					4543.15 l/s\$3600 7 days
Sub - Total				\$ 11,314.90	\$ 8,512.60

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered **Diagonally to the RH Side from rear to front; right to left;** portion of the vehicle.



The general area of damages is at the **RH Side portion**
(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Apex Motoring** is \$ 11,314.90 .
We have adjusted the cost to \$ 8,512.60 and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of \$ 6,810.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **8** working days.

34 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **6277** for our services rendered and
we thank you for engaging our services.


KELVIN TEO
Licensed Automotive Appraiser
Nitec in Automotive Technology
Cert. Crash Investigation & Reconstruction
Dip MS
MSAAA, AM SAE-A

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.