

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909**Our File No:** CS/CTI22010480/UQY3Q2**Date:** 16/11/2022REFERENCEInsured/Claimant: TEO SWEE HIANG Policy No: DMPCSNW00009672201  
Date of Loss: 03/10/2022 Nature of Claim: OD Claim No: SNM22D207119/C01/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMH7887R**  
Make & Model: NISSAN SYLPHY, 1.5 (A) Engine No: HR16937674C  
Reg. Date: 04/01/2019 (Man. Year: 2018) Chassis No: MNTBBAB17Z0033956  
Colour: White Odometer: 62946 km  
Engine Capacity: 1598 cc  
Market Value/New Car Price: S\$70,000.00  
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRESFront Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16  
Front Left Side: Bridgestone 3 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 3 mm Rear Right Side: Bridgestone 5 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,461.12	7,150.44	5,310.68	42.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	1,470.00	2,920.00	66.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,851.12</b>	<b>8,620.44</b>	<b>8,230.68</b>	<b>48.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,800.00</b>		
<b>- Excess (S\$)</b>	1,000.00	1,000.00	0.00	0.00
<b>(S\$)</b>	15,851.12	5,800.00	10,051.12	63.41
<b>+ GST 7.00/7.00% (S\$)</b>	1,109.58	406.00	703.58	63.41
<b>Nett Amount (S\$)</b>	<b>16,960.70</b>	<b>6,206.00</b>	<b>10,754.70</b>	<b>63.41</b>

INSPECTIONDate of Assignment: 21/10/2022  
Date Inspected: 25/10/2022 Inspected At: 56 Loyang Way, #04-04 Loyang Enterprise Building  
Repairer: AP Automotive Services Pte Ltd (HQ)  
Estimated Period of Repair: 5.0 days**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2022)
<b>Parts:</b> 143	NISSAN SYLPHY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMH7887R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	598.00 FL	*577.90 FL
2	2		*FRONT BUMPER FOGLAMP	Not Necessary	516.00 FL	*- FL
3	2		*FRONT BUMPER FOGLAMP GARNISH	Not Necessary	248.00 FL	*- FL
4	1		*FRONT BUMPER TOW HOOK COVER	Cut	29.00 FL	*20.00 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	290.00 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Torn	234.00 FL	*202.40 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	572.00 FL	*561.90 FL
8	1		*FRONT BUMPER ABSORBER BRACKET LH	No such part	216.20 FL	*- FL
9	2		*FRONT BUMPER SIDE RETAINER	Bent	48.20 FL	*48.20 FL
10	1		*FRONT BUMPER UNDERCOVER GARNISH	Not Necessary	202.00 FL	*- FL
11	2		*HEADLAMP	Holder Cracked	1,630.00 FL	*1,630.00 FL
12	2		*HEADLAMP INNER LOWER BRACKET	Cracked	58.00 FL	*50.00 FL
13	2		*HEADLAMP LOWER BRACKET	No such part	60.00 FL	*- FL
14	1		*CENTRAL GRILLE CHROME }	Broken	765.00 FL	*765.00 FL
15	1		*CENTRAL GRILLE }	Broken	250.00 FL	*- FL
16	2		*CENTRAL GRILLE TOP SUPPORT BRACKET	Bent	40.00 FL	*40.00 FL
17	1		*CENTRAL GRILLE LOGO	Scratched	65.00 FL	*48.00 FL
18	1		*BONNET	Buckled	911.40 FL	*891.20 FL
19	2		*BONNET HINGE	Bent	90.00 FL	*90.00 FL
20	1		*BONNET INSULATOR	Not Necessary	168.00 FL	*- FL
21	2		*BONNET STOPPER	Not Necessary	38.00 FL	*- FL
22	1		*BONNET LOCK	Bent	42.00 FL	*42.00 FL
23	1		*FRONT SUPPORT PANEL (TOP CENTRE)	Buckled	155.00 FL	*155.00 FL
24	1		*FRONT SUPPORT PANEL (LOWER CENTRE)	Repair	435.00 FL	*- FL
25	2		*FRONT SUPPORT PANEL (SIDE)	Repair	166.00 FL	*- FL
26	1		*FRONT SUPPORT PANEL TOP GARNISH	Distorted	404.00 FL	*125.00 FL
27	1		*FRONT SUPPORT BRACE PANEL	Bent	87.00 FL	*87.00 FL
28	1		*RADIATOR	Bent	970.00 FL	*785.00 FL
29	1		*RADIATOR SPARE TANK	Not Necessary	254.00 FL	*- FL
30	1		*RADIATOR FAN COWLING	Not Necessary	232.00 FL	*- FL
31	1		*AIR CONDENSOR	Bent	823.00 FL	*823.00 FL
32	1		*AIR CON CONDENSOR SIDE GARNISH	Torn	196.00 FL	*148.00 FL
33	2		*HORN	Not Necessary	202.00 FL	*- FL
34	1		*TEMPERATURE SENSOR	Not Necessary	138.00 FL	*- FL
35	1		*FRONT FUSE BOX	Not Necessary	150.00 FL	*- FL
36	1		*FRONT FENDER	N/S Repair / O/S Buckled	1,444.00 FL	*722.00 FL
37	2		*FRONT FENDER INNER COWLING	Not Necessary	230.00 FL	*- FL
38	1		*FRONT NUMBER PLATE	Bent	120.00 FS	*40.00 FS
39	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
40	1		*SET FRONT BUMPER UNDERCOVER GARNISH CLIP	Not Necessary	80.00 FS	*- FS
41	1		*SET CENTRAL GRILLE CLIP	Not Necessary	60.00 FS	*- FS
42	1		*SET BONNET INSULATOR CLIP	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
44	1		*SET AIR CON CONDENSOR SIDE GARNISH CLIP	Not Necessary	60.00 FS	*- FS
45	2		*SET FRONT FENDER COWLING CLIP	Not Necessary	160.00 FS	*- FS
46	1		*RADIATOR COOLANT	Necessary	120.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,756.80</b>	<b>7,931.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,295.68	781.16
<b>Total Parts (\$\$)</b>	<b>12,461.12</b>	<b>7,150.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	750.00
3	CHECK WIRING AND HEAD LAMP FUNCTIONS	New	120.00	20.00
4	REMOVE AND REFIT A/C CONDENSER AND REFILL A/C GAS	New	120.00	100.00
5	REMOVE AND REFIT REVERSE SENSOR AND CHECK FUNCTIONS	New	260.00	0.00
6	REMOVE AND REFIT RADIATOR AND CONDUCT PRESSURE TEST	New	350.00	0.00
7	COMPUTERISED DIAGNOSTIC TEST AND CLEAR FAULT CODES	New	300.00	0.00
8	TO APPLY RUST PROOFING	New	240.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>4,390.00</b>
				<b>1,470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >