



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 986G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	NOT NECESSARY	168.00	-
2	FRONT FORK TUBE ASSY	NOT NECESSARY	640.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	220.00	-
2	FRONT SIDE COVER	N/S NOT NECESSARY / O/S CUT	440.00	180.00
1	FRONT RIM	NOT NECESSARY	340.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING	NOT NECESSARY	70.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	180.00	-
1	HEADLAMP (LED)	CRACKED	1,550.00	980.00
1	HEADLAMP COVER	CRACKED	228.00	150.00
1	SET FRONT SIGNALS	CRACKED	216.00	152.00
1	HANDLE BAR	BENT	180.00	180.00
1	SET HANDLE BAR BALANCER	N/S CUT	98.00	38.00
1	SET HAND GRID	NOT NECESSARY	58.00	-
1	MIRROR (N/S)	CUT	110.00	110.00
2	BRAKE LEVER	N/S CUT	130.00	65.00
1	SET FOOTSTEP PANEL	O/S CUT	250.00	125.00
1	FOOTSTEP LOWER PANEL	CUT	320.00	190.00
1	EXHAUST ASSY	NOT NECESSARY	980.00	-
1	EXHAUST FRONT COVER	NOT NECESSARY	105.00	-
1	EXHAUST CENTRE COVER	CUT	125.00	125.00
1	EXHAUST END CAP	CRACKED	95.00	95.00
1	AIR FILTER COVER	SCRATCHED	195.00	195.00
1	SIDE STAND	BENT	135.00	135.00
1	MAIN STAND	CUT	185.00	185.00
	LESS 10% DISCOUNT		-706.30	-290.50
			6,356.70	2,614.50
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	NOT NECESSARY	38.00	-

Report Ref No. CS/AGI22010485/Uny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	BEARING CONE (SN)	NOT NECESSARY	95.00	-
1	REAR BOX (SN)	CRACKED	580.00	350.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
			979.00	350.00
	LABOUR			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING .	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR.		480.00	300.00
			1,040.00	300.00
GRAND TOTAL			8,375.70	3,264.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/AGI22010485/Uny3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.