

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9622E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, REAR BUMPER	TO REPAIR SEE LABOUR	442.60	-
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	NOT NECESSARY	332.70	-
1	COVER, REAR BUMPER, LOWER	SERVICEABLE	15.40	-
1	GIARD, REAR BUMPER, CENTER	NOT NECESSARY	576.30	-
1	RETAINER, REAR BUMPER SIDE, RH	NOT NECESSARY	117.70	-
1	RETAINER, REAR BUMPER SIDE, LH	NOT NECESSARY	116.50	-
1	LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	NOT NECESSARY	451.80	-
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (LOWER)	NOT NECESSARY	261.00	-
1	COVER, REAR COMBINATION LAMP, RH	NOT NECESSARY	64.50	-
1	COVER, FLOOR UNDER, NO.1 LH	NOT NECESSARY	175.10	-
1	COVER, FLOOR UNDER, NO.2 RH	NOT NECESSARY	241.90	-
1	COVER, REAR FLOOR CTR	NOT NECESSARY	229.90	-
1	COVER, DECK TRIM, REAR	NOT NECESSARY	126.70	-
1	PANEL SUB-ASSY, BODY LOWER BACK	NOT NECESSARY	650.30	-
	LESS 25% DISCOUNT		-950.60	-
			2,851.80	-
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	95.00	-
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER PROTECTOR (SN)	NOT FITTED	180.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	85.00	-
1	END PANEL TRIM CLIP (SN)	NOT NECESSARY	65.00	-
			1,225.00	100.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-

Report Ref No. CS/AGI22010486/Dny3e2



Description of Parts

PANEL BEATING, KNOCKING AND STRAIGHTEN THE

Qty

LKK Auto Consultants Pte Ltd

Condition

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Our Adjusted

(\$)

200.00

Estimate By

Workshop (\$))

2,200.00

RECOMMENDED COST OF REPAIRS			500.0
GRAND TOTAL		12,466.80	500.0
		8,390.00	400.0
TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	380.00	
TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	220.00	
TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	
TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	
TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	200.0
TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	
TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	
TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	480.00	
TO REMOVE AND REFIT ELECTRICAL WIRING, BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	480.00	
TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	
TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	
NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF COVER, REAR BUMPER.			

Report Ref No. CS/AGI22010486/Dny3e2



Automotive Assessor / Investigator