

**Speedwerkz Pte Ltd**

13 KAKI BUKIT ROAD 4 #01-20

Singapore 417807

+65 96195936

info@speedwerkz.biz

**Estimate**ADDRESS  
SMV6660KESTIMATE      1148  
DATE            25/07/2022

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
		LUMP SUM REPAIR AS RECOMMENDED & AGREED WITH SURVEYOR	1	5,800.00	5,800.00

TOTAL

**S\$5,800.00**

Accepted By

Accepted Date

# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647. Singapore 542224

Email: [Winsongkk@hotmail.com](mailto:Winsongkk@hotmail.com) Contact: 9747 0063

Company Register No. 53326249J

---

Our Ref: WG/TP/2022-189  
Invoice No: TP/LSW/2022-189  
Vehicle No: SMV6660K  
Attn: KERK TECK ANN  
Company: SPEEDWERKZ PTE LTD  
Address: BARTLEY BIZ CENTRE , 13 KAKI BUKIT ROAD, #01-20. SINGAPORE 417807

Date 25 July 2022

## Invoice

Surveyor Fee:	S\$380
Re-inspection Fee:	S\$80
Transport:	S\$60
Photographs:	S\$66- (@ \$1 per photo, total 66 photos)
Total:	S\$586

Surveyor:  
Signature:  
Date:

Winson Goh

25 July 2022



# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647. Singapore 542224

Email: winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

## ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : KERK TECK ANN  
C/O SPEEDWERKZ PTE LTD  
BARTLEY BIZ CENTRE , 13 KAKI BUKIT ROAD, #01-20  
SINGAPORE 417807

Date : 25 July 2022  
Our Ref : WG/TP/2022-189

### REFERENCE PARTICULARS

Date of Accident : 17 April 2022  
Date of Inspection : 22 June 2022

Type of Inspection : Third Party Claim  
Date of Re-Inspn : 22 June 2022

### VEHICLE PARTICULARS

Registration No : SMV6660K  
Make : HONDA  
Model : CIVIC 1.6 VTI CVT  
Year : 2017

Engine No : R16B22000109  
Chassis No : MRHFC5650HT000086  
Odometer : 224670km  
Colour : White

### CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front Near side	: Yokohana	185/40R18	5 mm
Front Off Side	: Yokohana	185/40R18	5 mm
Rear Near Side	: Yokohana	185/40R18	5 mm
Rear off Side	: Yokohana	185/40R18	5 mm

### GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front portions..  
For details, refer to assessment for repairs and photographs attached.

### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$5,800.00** nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five ( 05 ) working days.

Enclosed Sixty-Six ( 66 ) photographs depicting damage to the vehicle.

Inspection conducted at : SPEEDWERKZ PTE LTD  
BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD, #01-20. SINGAPORE 417807

In accordance to your instruction, we have **not authorise** repairs and inspection  
was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : SMV6660K  
MODEL : CIVIC 1.6 VTI CVT

Our Ref : WG/TP/2022-189

**ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS**

**DESCRIPTION OF PARTS AND NATURE OF REPAIRS**

A)	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
01	FRONT BUMPER	1	DEFORMED/CRACKED	\$ 728.00	\$ 728.00
02	FRONT BUMPER RETAINER LH	1	NECESSARY	\$ 58.00	\$ 58.00
03	FRONT BUMPER RETAINER RH	1	NECESSARY	\$ 58.00	\$ 58.00
04	FRONT FOG LAMP COVER LH	1	NOT NECESSARY	\$ 109.00	\$ -
05	FRONT FOG LAMP COVER RH	1	NOT NECESSARY	\$ 109.00	\$ -
06	FRONT FOG LAMP LH	1	NOT NECESSARY	\$ 289.00	\$ -
07	FRONT FOG LAMP RH	1	NOT NECESSARY	\$ 289.00	\$ -
08	FRONT HEADLAMP LH	1	CRACKED	\$ 830.00	\$ 830.00
09	FRONT HEADLAMP RH	1	NOT NECESSARY	\$ 830.00	\$ -
10	FRONT SUPPORT PANEL TOP GARNISH	1	GRAZED/DEFORMED	\$ 113.00	\$ 113.00
				\$ 3,413.00	\$ 1,787.00
			Less 20%	\$ 682.60	\$ 357.40
				\$ 2,731.00	\$ 1,429.60

**B) S/NETT ITEM**

11	FRONT NUMBER PLATE	1	BENT	\$ 100.00	\$ 90.00
12	FRONT BONNET ( CARBON FILBER )	1	CRACKED	\$ 1,800.00	\$ 1,600.00
13	FRONT GRILLE ( CARBON FILBER )	1	CRACKED	\$ 1,400.00	\$ 1,200.00
14	FRONT HEADLAMP LIP LH ( CARBON FILBER )	1	CRACKED	\$ 550.00	\$ 400.00
15	FRONT HEADLAMP LIP RH ( CARBON FILBER )	1	NOT NECESSARY	\$ 550.00	\$ -
16	FRONT BUMPER LOWER LIP ( CARBON FILBER )	1	CRACKED	\$ 980.00	\$ 980.00
17	FRONT BUMPER CLIP	1 SET	NECESSARY	\$ 50.00	\$ 40.00
18	FRONT GRILLE CLIP	1 SET	NECESSARY	\$ 40.00	\$ 30.00
				\$ 5,470.00	\$ 4,340.00

**Parts Total :** \$ 8,201.00 \$ 5,769.60

**C) LABOUR CHARGES & MISC**

19	CHECK FRONT WIRING AND LIGHTNING SYSTEM	\$ 100.00	\$ 90.00
20	PANEL BEATING ON AFFECTED AREA AND RENEW DAMAGE PARTS	\$ 700.00	\$ 600.00
21	SPRAY PAINTING ON AFFECTED AREAS	\$ 800.00	\$ 700.00
22	APPLY ANTI RUST ON AFFECTED AREAS	\$ 150.00	\$ 120.00
	<b>Labour Total :</b>	\$ 1,750.00	\$ 1,510.00

**Total Parts and Laboure :** \$ 9,951.00 \$ 7,279.60

**FINAL LUMP SUM ADJUSTMENT**

\$ 5,800.00

#### POINT OF IMPACT

The impact was confined to the front portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.

#### ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

#### CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **S\$5,800.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
WG APPRAISAL SERVICES



Winson Goh  
Automotive Appraiser