



Your Ref: 2022 - 38

Date: 22nd Nov 2022

Our Ref: CS1/SCD22010487/Tqy3e2

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMV 6660K

INSURED VEHICLE: QX 1275P

ACCIDENT DATE: 17/04/2022

We thank you for your instruction on 20/10/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMV 6660K from M/s WG Appraisal Services.
- b) Final Repair Bill of SMV 6660K from M/s Speedwerkz Pte Ltd.
- c) Colour damaged vehicle photographs of SMV 6660K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|-----------------------|
| Registration Number | : SMV 6660K |
| Make & Model | : Honda Civic VTI CVT |
| Chassis Number | : MRHFC5650HT000086 |
| Year of Registration | : 2017 |

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 6660K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|--------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT BUMPER | DEFORMED / CRACKED | 728.00 | 579.20 |
| 1 | FRONT BUMPER RETAINER LH | NECESSARY | 58.00 | 58.00 |
| 1 | FRONT BUMPER RETAINER RH | NOT NECESSARY | 58.00 | - |
| 1 | FRONT FOG LAMP COVER LH | NOT NECESSARY | 109.00 | - |
| 1 | FRONT FOG LAMP COVER RH | NOT NECESSARY | 109.00 | - |
| 1 | FRONT FOG LAMP LH | NOT NECESSARY | 289.00 | - |
| 1 | FRONT FOG LAMP RH | NOT NECESSARY | 289.00 | - |
| 1 | FRONT HEADLAMP LH | CRACKED | 830.00 | 830.00 |
| 1 | FRONT HEADLAMP RH | NOT NECESSARY | 830.00 | - |
| 1 | FRONT SUPPORT PANEL TOP GARNISH | GRAZED / DEFORMED | 113.00 | 113.00 |
| | LESS 20% DISCOUNT | | -682.60 | -316.04 |
| | | | 2,730.40 | 1,264.16 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | FRONT NUMBER PLATE (SN) | NOT NECESSARY | 100.00 | - |
| 1 | FRONT BONNET (CARBON FILBER) (SN) | CRACKED | 1,800.00 | 1,200.00 |
| 1 | FRONT GRILLE (CARBON FILBER) (SN) | CRACKED | 1,400.00 | 700.00 |
| 1 | FRONT HEADLAMP LIP LH (CARBON FILBER) (SN) | CRACKED | 550.00 | 250.00 |
| 1 | FRONT HEADLAMP LIP RH (CARBON FILBER) (SN) | NOT NECESSARY | 550.00 | - |
| 1 | FRONT BUMPER LOWER LIP (CARBON FILBER) (SN) | NOT NECESSARY | 980.00 | - |
| 1 | SET FRONT BUMPER CLIP (SN) | NECESSARY | 50.00 | 40.00 |
| 1 | SET FRONT GRILLE CLIP (SN) | NECESSARY | 40.00 | 30.00 |
| | | | 5,470.00 | 2,220.00 |
| <u>LABOUR</u> | | | | |
| | CHECK FRONT WIRING AND LIGHTNING SYSTEM. | | 100.00 | 30.00 |
| | PANEL BEATING ON AFFECTED AREA AND RENEW DAMAGE PARTS. | | 700.00 | 400.00 |
| | SPRAY PAINTING ON AFFECTED AREAS. | | 800.00 | 400.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|------------------------------------|---------------|---------------------------|-------------------|
| | APPLY ANTI RUST ON AFFECTED AREAS. | NOT NECESSARY | 150.00 | - |
| | | | 1,750.00 | 830.00 |
| GRAND TOTAL | | | 9,950.40 | 4,314.16 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 3,450.00 |

Report Ref No. CS1/SCD22010487/Tqy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.