



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 6660K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED / CRACKED	728.00	579.20
1	FRONT BUMPER RETAINER LH	NECESSARY	58.00	58.00
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	58.00	-
1	FRONT FOG LAMP COVER LH	NOT NECESSARY	109.00	-
1	FRONT FOG LAMP COVER RH	NOT NECESSARY	109.00	-
1	FRONT FOG LAMP LH	NOT NECESSARY	289.00	-
1	FRONT FOG LAMP RH	NOT NECESSARY	289.00	-
1	FRONT HEADLAMP LH	CRACKED	830.00	830.00
1	FRONT HEADLAMP RH	NOT NECESSARY	830.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	GRAZED / DEFORMED	113.00	113.00
	LESS 20% DISCOUNT		-682.60	-316.04
			2,730.40	1,264.16
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	100.00	-
1	FRONT BONNET (CARBON FILBER) (SN)	CRACKED	1,800.00	1,200.00
1	FRONT GRILLE (CARBON FILBER) (SN)	CRACKED	1,400.00	700.00
1	FRONT HEADLAMP LIP LH (CARBON FILBER) (SN)	CRACKED	550.00	250.00
1	FRONT HEADLAMP LIP RH (CARBON FILBER) (SN)	NOT NECESSARY	550.00	-
1	FRONT BUMPER LOWER LIP (CARBON FILBER) (SN)	NOT NECESSARY	980.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	40.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	40.00	30.00
			5,470.00	2,220.00
<u>LABOUR</u>				
	CHECK FRONT WIRING AND LIGHTNING SYSTEM.		100.00	30.00
	PANEL BEATING ON AFFECTED AREA AND RENEW DAMAGE PARTS.		700.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	400.00

Report Ref No. CS1/SCD22010487/Tqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			1,750.00	830.00
GRAND TOTAL			9,950.40	4,314.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,450.00

Report Ref No. CS1/SCD22010487/Tqy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.