

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS22010489/CWY3M4**Date:** 27/12/2022**REFERENCE**

Insured/Claimant:	AWANG BIN HAMID	Policy No:	SP2002660176	
Date of Loss:	15/10/2022	Nature of Claim:	OD	Claim No: 202222007489

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFL963L		
Make & Model:	MAZDA CX-30, 2.0 ELEGANCE (A)	Engine No:	PE31574512
Reg. Date:	24/08/2020 (Man. Year: 2020)	Chassis No:	JM6DM2W7AL0101107
Colour:	Grey	Odometer:	55145 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$122,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,307.50	2,398.00	2,909.50	54.82
Miscellaneous Items	300.00	30.00	270.00	90.00
Labour	1,200.00	510.00	690.00	57.50
Paintwork Labour	800.00	500.00	300.00	37.50
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,607.50	3,438.00	4,169.50	54.81
- Excess (\$\$)	700.00	700.00	0.00	0.00
(\$\$)	6,907.50	2,738.00	4,169.50	60.36
+ GST 7.00/7.00% (\$\$)	483.53	191.66	291.87	60.36
Nett Amount (\$\$)	7,391.03	2,929.66	4,461.37	60.36

INSPECTION

Date of Assignment:	21/10/2022	Present Location:	Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected:	25/10/2022	Inspected At:	Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane Singapore 739145
Estimated Period of Repair:	3.0 days		

Adjuster: SIMON HO LEONG CHUAN**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2022)	
Parts: M1-SUV	MAZDA CX-30 2.0 ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SFL963L)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN (WCP)	Broken	520.00 F	*520.00 F
2	1		*REAR TAILGATE (WCP)	Dented	820.00 F	*820.00 F
3	1		*REAR BUMPER (WCP)	Repair	580.00 F	*- F
4	1		*REAR WINDSCREEN MOULDING (NPA)	Not Necessary	-	-
5	1		*REAR TAILGATE UPPER MOULDING (NPA)	Not Necessary	-	-
6	1		*REAR TAILGATE CENTER MOULDING (WCP)	Broken	420.00 F	*420.00 F
7	1		*REAR TAILGATE HINGE RH (WCP)	Serviceable	35.00 F	*- F
8	1		*REAR TAILGATE HINGE LH (WCP)	Serviceable	35.00 F	*- F
9	1		*REAR TAILGATE LOCK (WCP)	Not Necessary	540.00 F	*- F
10	1		*REAR TAILLAMP OUTER LH (WCP)	Not Necessary	280.00 F	*- F
11	1		*REAR TAILLAMP INNER LH (WCP)	Broken	420.00 F	*420.00 F
12	1		*REAR TAILLAMP INNER RH (WCP)	Not Necessary	420.00 F	*- F
13	1		*REAR TAILLAMP OUTER RH (WCP)	Not Necessary	280.00 F	*- F
14	1		*REAR BUMPER REFLECTOR RH (WCP)	Not Necessary	45.00 F	*- F
15	1		*REAR BUMPER REFLECTOR LH (WCP)	Not Necessary	45.00 F	*- F
16	1		*REAR BUMPER REINFORCEMENT (WCP)	Not Necessary	385.00 F	*- F

F=Franchise part.

Sub Total (S\$)	4,825.00	2,180.00
+ Margin on L,N Items 10.00/10.00% (S\$)	482.50	218.00
Total Parts (S\$)	5,307.50	2,398.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR BUMPER CLIPS (Necessary)	50.00	30.00
2	1	REAR PARKING SENSORS (Not Necessary)	250.00	0.00
Sub Total (\$\$)			300.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	LABOUR FOR SPRAY PAINTING	New	800.00	500.00
Labour Items				
2	LABOUR FOR PANEL BEATING	New	800.00	400.00
3	LABOUR TO REMOVE & REFIT REAR TAILGATE MECHANISM	New	200.00	60.00
4	LABOUR TO REMOVE & REFIT REAR PARKING SENSORS	New	200.00	50.00
Gross Labour Cost (\$\$)			2,000.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >