



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 5417H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	CAP	MISSING	78.00	78.00
1	PROTECTOR MUFFLER	CRACKED	110.00	110.00
1	MUFFLER COMP 1	BROKEN	384.00	384.00
1	KICK CRACK ASSY	CUT	65.00	65.00
1	FENDER FRONT	CUT	119.00	119.00
1	COVER REAR FENDER	CRACKED / GRAZED	154.00	154.00
1	PANEL 2	NOT NECESSARY	311.00	-
1	COVER SIDE 2	NOT NECESSARY	209.00	-
1	GRAPHIC 2	NOT NECESSARY	54.00	-
1	COVER SIDE 4	NOT NECESSARY	311.00	-
1	GRAPHIC 3	NOT NECESSARY	54.00	-
1	COVER SIDE 1	NOT NECESSARY	264.00	-
1	GRAPHIC 1	NOT NECESSARY	34.00	-
1	COVER 5	NOT NECESSARY	231.00	-
1	REAR ARM COMP	NOT NECESSARY	650.00	-
1	REAR FENDER COMP	NOT NECESSARY	211.00	-
1	STAY HEADLAMP	NOT NECESSARY	109.00	-
1	CROWN HANDLE	NOT NECESSARY	122.00	-
1	FRONT FORK ASSY LH	NOT NECESSARY	350.00	-
1	FRONT FORK ASSY RH	NOT NECESSARY	350.00	-
1	TANK SIDE COVER 2	CUT	157.00	157.00
1	GRAPHIC 3	NECESSARY	23.00	23.00
1	TANK SIDE COVER 1	NOT NECESSARY	157.00	-
1	GRAPHIC FUEL TANK 2	NOT NECESSARY	23.00	-
1	HANDLE BAR	BENT	355.00	355.00
1	END GRIP ASSY RH	GRAZED	55.00	55.00
1	RH LEVER	GRAZED	87.00	87.00
1	PEDAL BRAKE	BENT	109.00	109.00
1	BRACKET FOOTREST 2	BENT	211.00	211.00
1	FOOTREST	BENT	57.00	57.00

Report Ref No. CS3/ASM22002277/Cqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FLASHER LIGHT ASSY RH	CRACKED	112.00	112.00
1	REAR FLASHER LIGHT ASSY RH	NOT NECESSARY	109.00	-
1	HEADLAMP ASSY	NOT NECESSARY	411.00	-
1	COVER UPPER	NOT NECESSARY	219.00	-
1	COVER OUTER 2	NOT NECESSARY	125.00	-
1	REAR VIEW MIRROR LH	NOT NECESSARY	67.00	-
1	REAR VIEW MIRROR RH	GRAZED	67.00	67.00
	LESS 10% DISCOUNT		-651.40	-214.30
			5,862.60	1,928.70
	<u>SPECIAL NETT ITEMS</u>			
1	GEAR SHIT SHAFT OIL SEAL (SN)	NOT NECESSARY	24.00	-
1	FORK OIL SEAL (SN)	NOT NECESSARY	120.00	-
1	FORK OIL (SN)	NOT NECESSARY	60.00	-
1	REAR BOX (SN)	NOT NECESSARY	550.00	-
1	REAR BOX BRACKET (SN)	NOT NECESSARY	210.00	-
1	SIDE BOX RH (SN)	NOT FITTED	400.00	-
1	SIDE BOX RACKET RH (SN)	NOT FITTED	190.00	-
1	SIDE BOX LH (SN)	NOT NECESSARY	400.00	-
1	SIDE BOX BRACKET LH (SN)	NOT NECESSARY	190.00	-
			2,144.00	-
	<u>LABOUR</u>			
	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM.		600.00	200.00
	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING.	NOT NECESSARY	380.00	-
	TO REMOVE / REFIT, REPLACE FRONT FORK TUDES.	NOT NECESSARY	250.00	-
	SPRAY PAINTING.		380.00	150.00
			1,610.00	350.00
	GRAND TOTAL		9,616.60	2,278.70



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00
---	--	--	-----------------

Report Ref No. CS3/ASM22002277/Cqy3e2-1

HO LEONG CHUAN
Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**