

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S CHIA BACK CHOY
C/O MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
Singapore 408934

Date : 29 August 2019
Our Ref : WG/TP/2019-313

REFERENCE PARTICULARS

Date of Accident : 13 August 2019
Date of Inspection : 27 August 2019

Type of Inspection : Third Party Claim
Date of Re-Inspn : 27 August 2019

VEHICLE PARTICULARS

Registration No : JKL9741
Make : TOYOTA
Model : AVANZA
Year : 2007

Engine No : FM37300
Chassis No : PR2F601MC002537005
Odometer : 375671km
Colour : Green

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near side	Goodyear	195/60R15
Front Off Side	Goodyear	195/60R15
Rear Near Side	Goodyear	195/60R15
Rear off Side	Goodyear	195/60R15

Thread Balance
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear right portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was S\$2,400.00 nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Five (05) working days.

Enclosed Twenty-eight (28) photographs depicting damage to the vehicle.

Inspection conducted at : MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park . Singapore 408934

In accordance to your instruction, we have not authorise repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".

VEHICLE NO : JKL9741
 MODEL : AVANZA

Our Ref : WG/TP/2019-313

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

<u>DESCRIPTION OF PARTS AND NATURE OF REPAIRS</u>			<u>ORIGINAL QUOTATION</u>	<u>REVISED QUOTATION</u>
	<u>QTY</u>	<u>ASSESSED CONDITION</u>		
	<u>PC/SET</u>			
<u>SPARE PARTS</u>				
1	1	REAR BUMPER	\$ 719.40	\$ 719.40
2	2	REAR BUMPER BRACKET	\$ 120.30	\$ 120.30
3	1	REAR RH FENDER	\$ -	\$ -
4	1	REAR RH DOOR	\$ -	\$ -
			\$ 839.70	\$ 839.70
			\$ 209.92	\$ 209.92
		Less 25%	\$ 629.78	\$ 629.78
B)	<u>SNETT ITEM</u>		\$ 800.00	\$ 700.00
5	REAR BUMPER LOWER GANRISH	1	\$ 30.00	\$ 20.00
6	REAR BUMPER CLIP	1 SET	\$ 830.00	\$ 720.00
		Parts Total :	\$ 1,459.78	\$ 1,349.78
C)	<u>LABOUR CHARGES & MISC</u>		\$ 60.00	\$ 50.00
7	CHECK REAR WIRING AND LIGHTNING SYSTEM		\$ 120.00	\$ 100.00
8	REMOVE AND REFIT REAR REVERSE SENSOR		\$ 600.00	\$ 500.00
9	PANEL BEATING ON AFFECTED AREAS		\$ 1,000.00	\$ 900.00
10	SPRAY PAINTING ON AFFECTED AREAS		\$ 120.00	\$ 100.00
11	APPLY ANTI RUST ON AFFECTED AREAS		\$ 1,900.00	\$ 1,650.00
		Labour Total :	\$ 1,900.00	\$ 1,650.00
		Total Parts and Labour :	\$ 3,359.78	\$ 2,999.78

FINAL LUMP SUM ADJUSTMENT

\$ 2,400.00

3 days