



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JKL 9741

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	719.40	719.40
2	REAR BUMPER BRACKET	NECESSARY	120.30	120.30
1	REAR RH FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR RH DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-209.93	-209.93
			629.77	629.77
SPECIAL NETT ITEMS				
1	REAR BUMPER LOWER GARNISH (SN)	NOT NECESSARY	800.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	20.00
			830.00	20.00
LABOUR				
	CHECK REAR WIRING AND LIGHTNING SYSTEM.		60.00	30.00
	REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	30.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR RH FENDER AND REAR RH DOOR.		600.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	30.00
			1,900.00	890.00
GRAND TOTAL			3,359.77	1,539.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS3/ASM19014665/Ea3e2-1

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.