

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22010490/TCM4
Date: 28/04/2023**REFERENCE**

Insured/Claimant:	CHONG MINGYONG	Policy No:	1700087379	
Date of Loss:	18/10/2022	Nature of Claim:	OD	Claim No: 1229288349SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7364B		
Make & Model:	AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZ584011
Reg. Date:	12/12/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V9J1024727
Colour:	Red	Odometer:	76601 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$89,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	75,850.00	38,609.60	37,240.40	49.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	48,084.00	29,104.00	18,980.00	39.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	123,934.00	67,713.60	56,220.40	45.36
Approved Total (Overridden) (S\$)		52,000.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	123,334.00	51,400.00	71,934.00	58.32
+ GST 8.00/8.00% (S\$)	9,866.72	4,112.00	5,754.72	58.32
Nett Amount (S\$)	133,200.72	55,512.00	77,688.72	58.32

INSPECTION

Date of Assignment:	25/10/2022	
Date Inspected:	21/10/2022	Inspected At: 24 BENOI SECTOR SINGAPORE 629857
Estimated Period of Repair:	27.0 days	REPAIRER: PREMIUM AUTOMOBILES PTE LTD

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,432.00 FS	*1,945.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH / RH	N/s Cracked	86.00 FS	*34.24 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	179.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	571.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH / RH	N/s Cracked	636.00 FS	*254.40 FS
7	2		*FRONT BUMPER TRIM COVER - LH / RH	Not Necessary	364.00 FS	*- FS
8	2		*FRONT WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	84.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,578.00 FS	*1,262.40 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	210.00 FS	*168.00 FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	420.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	847.00 FS	*677.20 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	211.00 FS	*168.80 FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Deformed	136.00 FS	*108.80 FS
15	1		*HORN HIGH TONE - LH	Cracked	213.00 FS	*170.00 FS
16	1		*HORN LOW TONE - RH	Not Necessary	213.00 FS	*- FS
17	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
18	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
19	1		*FRONT FENDER - LH / RH	N/s Bent / O/s Not Necessary	1,908.00 FS	*763.20 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
21	1		*FRONT FENDER BRACKET - LH / RH	O/s Not Necessary/ N/s Bent	92.00 FS	*36.40 FS
22	11		*FRONT FENDER RIVET	Necessary	42.00 FS	*33.44 FS
23	1		*FRONT FENDER BRACE	Bent	107.00 FS	*85.60 FS
24	1		*FRONT WHEEL HOUSING LINER - LH / RH	N/s Cut	366.00 FS	*146.40 FS
25	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
26	1		*BONNET	Bent	3,348.00 FS	*2,678.40 FS
27	1		*BONNET ATTACHMENT PARTS	Not Necessary	172.00 FS	*- FS
28	2		*BONNET HINGE - LH / RH	Bent	136.00 FS	*108.48 FS
29	1		*BONNET EDGE PROTECTION	Necessary	31.00 FS	*24.72 FS
30	1		*BONNET CATCH HOOK	Bent	100.00 FS	*79.44 FS
31	2		*BONNET STRIKER - LH / RH	Bent	246.00 FS	*196.00 FS
32	1		*BONNET SIDE SEAL - LH	Not Necessary	46.00 FS	*- FS
33	1		*BONNET CATCH HOOK	Bent	71.00 FS	*56.32 FS
34	2		*BONNET LOCK - LH / RH	Bent	455.00 FS	*364.00 FS
35	1		*BONNET BOWDEN CABLE - CENTER	Cut	64.00 FS	*50.56 FS
36	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
37	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
38	1		*EXHAUST SOUND ABSORBER	Not Necessary	244.00 FS	*- FS
39	1		*PLENUM CHAMBER COVER	Cut	199.00 FS	*159.20 FS
40	2		*HEADLIGHT - LH / RH	O/s Cracked / N/s Cut	11,758.00 FS	*9,406.40 FS
41	2		*LIFT CYLINDER - LH / RH	Not Necessary	312.00 FS	*- FS
42	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
43	1		*LOCK CARRIER	Cracked	806.00 FS	*644.80 FS
44	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
45	1		*A/C CONDENSER	Bent	570.00 FS	*456.00 FS
46	1		*A/C CONDENSER REFRIGERATN LINE	Not Necessary	500.00 FS	*- FS
47	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	570.00 FS	*- FS
48	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	623.00 FS	*- FS
49	1		*RADIATOR ADDITIONAL COOLER	Bent	961.00 FS	*768.00 FS
50	1		*RADIATOR	Not Necessary	1,064.00 FS	*- FS
51	6		*READY-MIX COOLANT	Necessary	297.00 FS	*237.12 FS

LKK Auto Consultants Pte Ltd/SLU7364B/28/04/2023 12:52

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*RADIATOR FAN WITH FAN RING	Not Necessary	1,617.00 FS	*- FS
53	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	56.00 FS	*44.32 FS
54	1		*RADIATOR OUTER SEAL - RH	Necessary	9.00 FS	*7.12 FS
55	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Cracked	14.00 FS	*10.88 FS
56	1		*RADIATOR COVER	Cracked	30.00 FS	*23.84 FS
57	1		*RADIATOR AIR GUIDE	Cracked	59.00 FS	*46.56 FS
58	1		*RADIATOR WATER DRAINAGE HOSE	Not Necessary	37.00 FS	*- FS
59	1		*RADIATOR AIR GUIDE	Not Necessary	21.00 FS	*- FS
60	1		*RADIATOR AIR GUIDE	Not Necessary	69.00 FS	*- FS
61	1		*RADIATOR AIR FILTER	Not Necessary	337.00 FS	*- FS
62	1		*RADIATOR INTAKE MANIFOLD	Not Necessary	788.00 FS	*- FS
63	1		*FRONT WINDSCREEN	Not Necessary	1,206.00 FS	*- FS
64	1		*FRONT WINDSCREEN RAIN SENSOR GEL FOIL	Not Necessary	131.00 FS	*- FS
65	1		*SPRING CLIP	Not Necessary	23.00 FS	*- FS
66	1		*WINDSCREEN PRIMER	Not Necessary	22.00 FS	*- FS
67	1		*WINDSCREEN WATER DEFLECTOR STRIP - LH	Deformed	104.00 FS	*82.80 FS
68	1		*WINDOW SLOT SEAL TRIM STRIP - LH	Not Necessary	346.00 FS	*- FS
69	1		*WINDOW GUIDE TRIM STRIP - LH	Not Necessary	287.00 FS	*- FS
70	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
71	1		*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
72	1		*REAR BUMPER	Deformed	2,317.00 FS	*1,853.60 FS
73	1		*REAR BUMPER FIXING PARTS	Not Necessary	201.00 FS	*- FS
74	1		*REAR WHEEL HOUSING LINER ADAPTER - LH / RH	N/s Not Necessary/O/s Deformed	84.00 FS	*33.60 FS
75	2		*REAR BUMPER GUIDE SECTION - LH / RH	N/s Cracked/ O/s Missing	36.00 FS	*28.80 FS
76	1		*REAR BUMPER LOCKING MECHANISM - LH / RH	N/s Not Necessary/O/s Necessary	67.00 FS	*26.48 FS
77	1		*REAR BUMPER SPOILER	Deformed	264.00 FS	*210.80 FS
78	1		*REAR BUMPER REFLECTOR - LH / RH	O/s Not Necessary/ N/s Cracked	92.00 FS	*36.48 FS
79	1		*REAR OUTER TAIL LIGHT - LH / RH	O/s Not Necessary/ N/s Cracked	1,948.00 FS	*778.80 FS
80	2		*REAR OUTER TAIL LIGHT TRIM - LH / RH	Scratched	68.00 FS	*52.96 FS
81	1		*REAR INNER TAIL LIGHT - LH / RH	N/s Cracked/ O/s Not Necessary	1,948.00 FS	*778.80 FS
82	2		*REAR INNER TAIL LIGHT TRIM - LH / RH	Not Necessary	68.00 FS	*- FS
83	2		*REAR LICENCE PLATE LIGHT - LH / RH	Not Necessary	210.00 FS	*- FS
84	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	642.00 FS	*513.20 FS
85	2		*REAR BUMPER BRACKET - LH / RH	Broken	63.00 FS	*49.84 FS
86	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	149.00 FS	*- FS
87	1		*REAR PARKING AID SENSOR - INNER / OUTER (4PIECES)	Missing (2Pieces Only)	1,062.00 FS	*424.00 FS
88	4		*REAR PARKING AID SEAL RING	Necessary	10.00 FS	*8.00 FS
89	1		*SET REAR BUMPER WIRING	Torn	572.00 FS	*457.20 FS
90	1		*REAR BUMPER AERIAL KEY ACCESS	Missing	79.00 FS	*62.88 FS
91	1		*REAR LID	Bent	3,657.00 FS	*2,925.60 FS
92	1		*REAR LID ATTACHMENT PARTS	Not Necessary	308.00 FS	*- FS
93	2		*REAR LID HINGE - LH / RH	Bent	570.00 FS	*456.00 FS
94	1		*REAR LID FLAP GASKET	Deformed	229.00 FS	*182.80 FS
95	1		*REAR LID LOCK STRIKER	Bent	56.00 FS	*44.40 FS
96	1		*REAR LID LOCK	Cut	211.00 FS	*168.80 FS
97	1		*REAR LID LOCK COVER	Cut	8.00 FS	*6.32 FS
98	1		*REAR LID LOCK ACTUATOR PUSH BUTTON	Not Necessary	1,478.00 FS	*- FS
99	1		*REAR LID LOCK ACTUATOR COVER	Not Necessary	18.00 FS	*- FS
100	1		*PACKING ADHESIVE	Necessary	21.00 FS	*16.80 FS
101	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
102	1		*A3 INSCRIPTION	Necessary	104.00 FS	*82.80 FS
103	1		*TFSI INSCRIPTION	Necessary	104.00 FS	*82.80 FS
104	1		*REAR SIDE PANEL - RH	Not Necessary	4,445.00 FS	*- FS
105	1		*REAR WINDOW	Not Necessary	905.00 FS	*- FS

LKK Auto Consultants Pte Ltd/SLU7364B/28/04/2023 12:52

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
106	1		*REAR QUARTER WINDOW - RH	Not Necessary	635.00 FS	*- FS
107	2		*WINDOW PRIMER	Not Necessary	44.00 FS	*- FS
108	1		*REAR FUEL POCKET	Not Necessary	100.00 FS	*- FS
109	1		*REAR FUEL POCKET HOSE	Not Necessary	20.00 FS	*- FS
110	2		*REAR WHEEL HOUSING LINER - LH / RH	Deformed	520.00 FS	*208.00 FS
111	1		*REAR VENT TRIM	Not Necessary	75.00 FS	*- FS
112	1		*REAR CROSS PANEL	Bent	379.00 FS	*303.20 FS
113	1		*REAR CROSS PANEL REINFORCEMENT	Bent	773.00 FS	*618.00 FS
114	2		*REAR CROSS PANEL CONNECTING PLATE - LH / RH	Bent	322.00 FS	*256.80 FS
115	1		*REAR CROSS PANEL BOTTOM PLATE	Bent	737.00 FS	*589.20 FS
116	1		*REAR CROSS PANEL MOUNT BRACKET	Bent	91.00 FS	*72.40 FS
117	1		*REAR CROSS PANEL TRIM	Deformed	171.00 FS	*136.80 FS
118	1		*REAR LUGGAGE COMPARTMENT FLOOR COVERING	Cracked	602.00 FS	*481.20 FS
119	1		*REAR LUGGAGE COMPARTMENT TRIM - RH	Not Necessary	841.00 FS	*- FS
120	1		*REAR LID TRIM PANEL	Torn	345.00 FS	*276.00 FS
121	1		*REAR STOWAGE COMPARTMENT	Deformed	105.00 FS	*84.00 FS
122	1		*REAR SILENCER	Not Necessary	825.00 FS	*- FS
123	2		*EXHAUST SYSTEM RETAINER	Not Necessary	95.00 FS	*- FS
124	1		*EXHAUST HEAT SHIELD	Not Necessary	180.00 FS	*- FS
125	2		*THREE-POINT AUTOMATIC SEAT BETL - LH / RH	Activated	2,454.00 FS	*1,963.20 FS
126	2		*SEAT BELT HEIGHT ADJUSTER - LH / RH	Activated	430.00 FS	*344.00 FS
127	1		*AIRBAG CONTROL UNIT	Activated	1,923.00 FS	*1,585.60 FS
128	1		*REAR FUEL POCKET	Not Necessary	100.00 FS	*- FS
129	1		*REAR FUEL POCKET HOSE	Not Necessary	20.00 FS	*- FS
130	2		*REAR WHEEL HOUSING LINER - LH / RH	Not Necessary	520.00 FS	*- FS
131	1		*REAR VENT TRIM	Not Necessary	75.00 FS	*- FS
132	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
133	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
134	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
135	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
136	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
137	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
138	1		*SUNDRIES	Necessary	1,000.00 FS	*99.60 FS
139	1		*LASHING EYE - LOWER	Cracked	26.00 FS	*20.24 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **75,850.00** **38,609.60**

LKK Auto Consultants Pte Ltd/SLU7364B/28/04/2023 12:52

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	280.00
5	TO RENEW FRONT WINDSCREEN	New	480.00	0.00
6	TO INSTALL SOLAR FILM FOR ALL AFFECTED GLASSES	New	400.00	0.00
7	TO CARRY OUT WATER SEEPAGE TEST FOR ALL THE AFFECTED WINDSCREEN	New	200.00	0.00
8	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,750.00
9	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, LHS FRONT DOOR AND LHS UPPER A-PILLAR	New	5,500.00	2,300.00
10	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	800.00
11	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
12	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	0.00
13	TO REMOVE AND REINSTALL REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
14	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
15	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
16	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT	New	1,800.00	1,800.00
17	TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY. RENEW ACCORDINGLY	New	2,800.00	2,800.00
18	TO REMOVE AND REINSTALL FUEL TANK ASSY	New	600.00	600.00
19	TO SETUP VEHICLE ON CAR-O-LINER FOR REPAIR	New	2,400.00	2,400.00
20	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.CUT OUT AND WELD REAR END PANELLING, SPARE WHEEL HOUSING AND RHS REAR FENDER. RE-ALIGN RHS REAR CHASSIS FRAME INTO POSITION. REPAIR LHS REAR FENDER. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	11,900.00	5,500.00
21	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANELLING AND SPARE WHEEL HOUSING	New	780.00	780.00
22	TO RESPRAY REAR BUMPER, REAR LID, HINGES, BOTH REAR FENDER, RHS SILL PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES, END PANELLING AND SPARE WHEEL HOUSING. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS	New	7,500.00	2,850.00

LKK Auto Consultants Pte Ltd/SLU7364B/28/04/2023 12:52

No	Particulars	Lab.Type	Repairer's	Amount
23	TO CARRY OUT WHEEL ALIGNEMENT	New	240.00	240.00
24	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (S\$)			48,084.00	29,104.00

LKK Auto Consultants Pte Ltd/SLU7364B/28/04/2023 12:52

< END OF ESTIMATES >