Adjuster Report 10/27/22, 3:56 PM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI22010491/KWCQ2

27/10/2022 Date:

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MN000417 **Claimant Vehicle**

SHF533C Insured Vehicle No: SLC2393U No:

19/10/2022 Nature of Claim: TP Claim No: M2205854 Date of Loss:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF533C**

Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZR2G97143

JTDKB3FU903092089 Reg. Date: 30/09/2020 (Man. Year: 2020) Chassis No:

Colour: Metallic Pearl White/Red Odometer: 125345 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: Sailun 7 mm Sailun 7 mm Rear Right Side: Sailun 7 mm Front Right Side: Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,392.40	1,070.55	2,321.85	68.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	485.00	4,615.00	90.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,492.40	1,555.55	6,936.85	81.68
+ GST 7.00/7.00% (S\$)	594.47	108.89	485.58	81.68
Nett Amount (S\$)	9,086.87	1,664.44	7,422.43	81.68

INSPECTION

Date of Assignment: 26/10/2022

Trans-cab Auto Services Pte Ltd (Ang Mo Kio) Date Inspected: 21/10/2022 Inspected At: 2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Oct 2022)

Parts: 144 TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHF533C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*COVER ,REAR BUMPER ,LOWER	Dented	22.00 FL	*22.00 FL
4	1		*COVER ,REAR BUMPER ,CENTER	Bent	374.50 FL	*374.50 FL
5	1		*SEAL ,REAR BUMPER SIDE ,LH	Serviceable	118.30 FL	*- FL
6	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	118.30 FL	*- FL
7	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	132.60 FL	*- FL
8	1		*RETAINER ,REAR BUMPER SIDE ,RH	Distorted	132.60 FL	*132.60 FL
9	1		*COVER ,REAR BUMPER LOWER	Repeated	22.00 FL	*- FL
10	1		*COVER ,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
11	1		*COVER ,FLOOR UNDER NO.2 (RH)	Serviceable	241.90 FL	*- FL
12	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
13	1		*COVER ,DECK TRIM REAR	Serviceable	126.70 FL	*- FL
14	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
15	1		*REAR BUMPER SIDE CLIP	Necessary	60.00 FS	*60.00 FS
16	1		*REAR BUMPER PROTECTOR	No such part	100.00 FS	*-FS
17	1		*SET PARKING AID	Serviceable	700.00 FS	*-FS
18	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*-FS
19	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	4,183.20	1,407.40
	- List Item Discount on L Items 25.00/25.00% (S\$)			790.80	336.85	
				Total Parts (S\$)	3,392.40	1,070.55

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF TIRE RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labour	r Cost (S\$)	5,100.00	485.00
	Report was unsubmitted during this pri	int-out.		

< END OF ESTIMATES >