

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22010494/UYA3Q2**Date:** 13/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_03

Claimant Vehicle No : SKA9191L **Insured Vehicle No :** GBH8943K

Date of Loss: 23/10/2022 Nature of Claim: TP Claim No: MFL2022D0006293

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA9191L**
 Make & Model: NISSAN KICKS PREMIUM, 1.2 L E-POWER (A) Engine No: HR12361513C
 Reg. Date: 06/08/2020 (Man. Year: 2020) Chassis No: MNTFEAP15Z0000454
 Colour: Red Odometer: 65654 km
 Engine Capacity: 1198 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,356.50	6,723.00	12,633.50	65.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,780.00	1,480.00	4,300.00	74.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,136.50	8,203.00	16,933.50	67.37
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	25,136.50	6,500.00	18,636.50	74.14
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,107.45		

INSPECTION

Date of Assignment: 25/10/2022

Date Inspected: 25/10/2022 Inspected At:

Estimated Period of Repair: 5.0 days

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
 Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Dec 2022)	
Parts:	N/A	NISSAN KICKS PREMIUM 1.2 L E-POWER (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA9191L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Badly Dented	1,615.00 F	*1,008.70 FL
2	1		*FRONT DOOR OUTER HANDLE O/S	Grazed	282.00 F	*121.50 FL
3	1		*FRONT DOOR OUTER HANDLE KNOB O/S	Grazed	60.00 F	*35.00 FL
4	1		*FRONT DOOR OUTER PROTECTOR O/S	Bent / Grazed	355.00 F	*241.00 FL
5	1		*FRONT DOOR INNER LOCK O/S	Shorted	453.00 F	*166.50 FL
6	1		*FRONT DOOR INNER RUBBER O/S	Necessary	218.00 F	*122.80 FL
7	1		*FRONT DOOR INNER HANDLE BRACKET O/S	Cracked	166.00 F	*145.50 FL
8	1		*FRONT DOOR INNER LOWER RUBBER O/S	Necessary	118.00 F	*60.00 FL
9	1		*FRONT DOOR INNER TRIM O/S	Deformed / Torn	688.10 F	*482.00 FL
10	2		*FRONT DOOR HINGES O/S	Bent	180.00 F	*180.00 FL
11	1		*FRONT DOOR CHECKER O/S	Twisted	121.00 F	*108.00 FL
12	1		*FRONT DOOR GLASS OUTER MOULDING O/S	Necessary	165.00 F	*115.00 FL
13	1		*FRONT DOOR GLASS O/S	Not Necessary	255.10 F	*- FL
14	1		*FRONT DOOR GLASS REGULATOR & MOTOR O/S	Bent / Jammed	855.30 F	*260.50 FL
15	1		*FRONT DOOR SPEAKER O/S	Not Necessary	250.00 F	*- FL
16	1		*FRONT DOOR A PILLAR O/S	Repair	882.00 F	*- FL
17	1		*CENTRE PILLAR O/S	Repair	1,488.20 F	*- FL
18	1		*CENTRE PILLAR INNER GARNISH O/S	Not Necessary	185.20 F	*- FL
19	1		*ROCKER PANEL GARNISH O/S	Grazed / Torn	1,299.10 F	*485.00 FL
20	1		*REAR DOOR O/S	Badly Dented	1,699.10 F	*978.30 FL
21	1		*REAR DOOR OUTER (PROTECTOR O/S)	Grazed	245.00 F	*240.00 FL
22	1		*REAR DOOR INNER RUBBER O/S	Necessary	182.00 F	*122.80 FL
23	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed / Torn	600.50 F	*455.00 FL
24	2		*REAR DOOR HINGES O/S	Bent	180.00 F	*180.00 FL
25	1		*REAR DOOR CHECKER O/S	Twisted	121.00 F	*108.00 FL
26	1		*REAR DOOR GLASS OUTER MOULDING O/S	Necessary	108.90 F	*108.90 FL
27	1		*REAR DOOR GLASS O/S	Not Necessary	255.00 F	*- FL
28	1		*REAR DOOR GLASS REGULATOR & MOTOR O/S	Bent / Shorted	755.00 F	*260.50 FL
29	1		*REAR DOOR SPEAKER O/S	Cracked	250.00 F	*165.00 FL
30	1		*REAR DOOR INNER STEP GARNISH O/S	Not Necessary	182.00 F	*- FL
31	1		*REAR DOOR INNER HANDLE BRACKET O/S	Not Necessary	205.00 F	*- FL
32	1		*REAR DOOR INNER CHANNEL RUBBER O/S	Not Necessary	285.00 F	*- FL
33	1		*REAR FENDER O/S	Repair	1,915.00 F	*- FL
34	1		*REAR FENDER OUTER PROTECTOR O/S	Grazed	542.00 F	*420.00 FL
35	1		*REAR FENDER QUARTER GLASS O/S	Not Necessary	305.00 F	*- FL
36	1		*REAR SPORT RIM O/S	Cut	1,200.00 FS	*550.00 FS
37	1		*REAR TYRE O/S	Not Necessary	200.00 FS	*- FS
38	1		*SET REAR DOOR FRAME BLACK STICKER O/S	Necessary	60.00 FS	*60.00 FS
39	1		*REAR DOOR VISOR O/S	Necessary	60.00 FS	*40.00 FS
40	1		*SET REAR DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 FS	*30.00 FS
41	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
42	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
43	1		*REAR FENDER QUARTER GLASS SEALANT O/S	Not Necessary	50.00 FS	*- FS
44	1		*FRONT DOOR VISOR O/S	Necessary	60.00 FS	*40.00 FS
45	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 FS	*30.00 FS
46	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Necessary	60.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

3/13/23, 10:22 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					19,356.50	7,380.00
- List Item Discount on L Items 0.00/10.00% (\$)					0.00	657.00
Total Parts (\$)					19,356.50	6,723.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	0.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	0.00
4	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	150.00	0.00
5	TO DISMANTLE & REPLACED REAR FENDER QUARTER GLASS O/S	New	100.00	0.00
6	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	200.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
8	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
9	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
10	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	600.00
12	TO PUTTY & SPRAY PAINTING	New	2,500.00	800.00
Gross Labour Cost (\$\$)			5,780.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >