1/17/23, 11:05 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI22010495/KQY3Q2

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Singapore 079909 Date: 17/01/2023

REFERENCE

Insured/Claimant: EDMUND TAN YONG SIANG Policy No: DMPCSNW00031962200

Date of Loss: 20/10/2022 Nature of Claim: OD Claim No: SNM22D207552/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMH5851G

 Make & Model:
 KIA CERATO, 1.6 SX (A)
 Engine No:
 G4FGJH715963

 Reg. Date:
 28/01/2019 (Man. Year: 2018)
 Chassis No:
 KNAF3416MK5027285

Colour: Metallic Grey Odometer: 52597 km

Engine Capacity: 1591 cc Market Value/New Car Price: \$\$85,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 2 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,645.00	1,755.00	5,890.00	77.04
Miscellaneous Items		0.00	0.00	0.00	
Labour		298.20	88.20	210.00	70.42
Paintwork Labour		296.87	250.27	46.60	15.70
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,240.07	2,093.47	6,146.60	74.59
	- Excess (S\$)	0.00	500.00	-500.00	
	(S\$)	8,240.07	1,593.47	6,646.60	80.66
	+ GST 7.00/7.00% (S\$)	576.80	111.54	465.26	80.66
	Nett Amount (S\$)	8,816.87	1,705.01	7,111.86	80.66

INSPECTION

Date of Assignment: 25/10/2022 Present Location: Ding Auto Pte Ltd (HQ)

BLK 10 #01-20 SIN MING IND EST SEC C

Date Inspected: 09/11/2022 Inspected At: SINGAPORE 575645

Repairer: Ding Auto Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jan 2023)

Parts: 143 KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMH5851G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part	No. Particulars	Condition	Repairer's	Amount			
1	1	*TOTAL PARTS		7,255.00 F	*1,365.00 F			
<u>Sup</u>	Supplementary #1							
2	1	*FRONT BUMPER UPPER GARNISH	Dented	30.00 F	*30.00 F			
3	1	*FRONT BUMPER LOWER COVER	Cracked	250.00 F	*250.00 F			
4	1	*PARKING SENSOR LH	Shorted	95.00 F	*95.00 F			
5	1	*FOG LAMP COVER RH	Dented	15.00 F	*15.00 F			
F=Fra	F=Franchise part.							
			Total Parts (S\$)	7,645.00	1,755.00			

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
<u>Pair</u>	ntwork Labour							
1	Total Paint Labour	New	184.80	147.00				
2	Total Paint Materials	New	112.07	103.27				
Lab	<u>Labour Items</u>							
3	Total Panel/Mechanical Labour	New	298.20	88.20				
		Gross Labour Cost (S\$)	595.07	338.47				
	Report w	vas unsubmitted during this print-out.						

< END OF ESTIMATES >