

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKB 3506Y
car city

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

NIL

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value:

\$ 85k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

735J

Vehicle: IN / OUT

Date:

Person Contacted:

LYA 40271

Veh No:

SKB 3506Y

Yr Regn:

20/05/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

BMW 523i

C.C

2497

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

122763

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAFP 32020C866167

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

225/50 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

hankook

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/10/22

D.O.I.

26/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

L.f.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

ok 10k.

ok until 30-04-2031

11/11/22 4/5 x 7000 insured Anson checked 3575.77, 3416)

Date/Time, File Pass to?

☐

Preli. Report

1) 1/1/4 trans

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

MER-00

Lump Sum / I.B.I. (\$

7000

Car City Auto Centre Pte Ltd
#01-198, Blk 9006 Tampines Street
93,
528840

Insurer Reference: SKB3506Y
Repairer Reference: OD/22059
Date calculated: 21/10/2022 6:07 PM

Full Report
Registration: SKB3506Y
Printed: 21/10/2022 6:08 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Anson Seah	Currency:	SGD
Claim Reference:	SKB3506Y	Date of Incident:	21/10/22
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	BMW		
Model:	5 SERIES F10		
Sub Model:	523 I		
Model Sheet Number:	01 42 01		
Registration:	SKB3506Y		
VIN number:	WBAFP32020C866167		
Odometer:	122739		
Model Specs			
FROM 03.2011	THROUGH LOAD SYSTEM	AIR CON AUTO 2-ZONES	O2 VOLUME
COMFORT ACCESS SYST	DIP REAR VIEW MIRROR	XENON HEADLAMPS	INTER LIGHT AMBIENCE
HEADLAMP WASHERS	DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY	AUTO TAILGATE CONTR
DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON	2.5 LTR 150KW	SPORT S-WHEEL LEATH
8-GEAR AUTOMATIC	TYRES 225/55 YR 17	WHEELS 8J X 17 ALLOY	INT MOULDING BLACK
TWO COAT METALLIC	TYRE W/FLAT RUNNING	PREPARE OFF VEHICLE	

*not Authorized
rsk*

Excess?

26/10/22

*L / S S
4 days*

Whp hls After rep

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle Condition

Vehicle Status

Pre-Accident Damage:


Date of Inspection:

Damage Areas

All

☐

Underbody

☐

Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	-------------------------	------------------------	------------------------	-------------------------	-------------------------	--------------------------	-----------

Fair

Fair

Spare Tyre Brand Tread (Spare), mm

HANKOOK

5

Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
51 11 656	R + R FRONT BUMPER		9.0	31.50
51 11 566	R + R BOTH FRONT BUMPER CARRIERS		7.0	24.50
51 11 551	R + R FRONT UPPER BUMPER CARRIER		4.0	14.00
51 11 592	REMOVE/REFIT FRONT BUMPER BAR TRIM (WITH FRONT BUMPER BAR REMOVED)		6.0	21.00
66 20 610	ADD/WORK PARK DISTANCE CONTROL		4.0	14.00
51 71 600)	R + R RADIATOR AIR GUIDE		2.0	7.00
63 12 520)	R + R LEFT HEADLAMP		5.0	17.50
63 12 524	RENEW L/HEADLAMP (REMOVED)		4.0	14.00
61 67 621	R + R L/HEADLAMP WASHER NOZZLE		2.0	7.00
51 71 538	R + R L/F WHEELHOUSE COVER FRONT		4.0	14.00
0741	L/F WING REPAIR		20.0*	70.00

Code	Description		WU	Price SGD
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	5.80	69.0	241.50
	Total of Labour			241.50

Paint

Paint Work

Time Basis 12 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
99 68 529	FRONT BUMPER PAINTING STAGE 2	16.0	56.00
99 35 509	L/F WING PAINTING STAGE 1	6.0	21.00
99 99 000	ADDITIONAL TIME FOR ONE MAIN WORK INCLUDES: MIX COLOUR AND SPRAY COLOUR SAMPLE	18.0	63.00

Total Paint	Hrs	WU	Price SGD
	3.30	40.0	140.00

Material Cost - Paint

	Price SGD
New Part Painting	71.50
Surface-/Blend Paint	13.50
Material-constant Metal	13.47
Total	98.47

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2022-10-19	Price SGD
0283	FRONT BUMPER COVER	51 11 7 285 961	Original	DIS —	1,450.00 —
0336	FRT UPP BUMPER SUPP	SEE GUIDE NO. 0333	Original	DD —	820.00 —
0340	FRT UPP IMPACT DAMP	51 11 7 200 707	Original	For —	85.00 —
0349	L/INN U-SONIC SENDER	66 20 9 270 495	Original	shock —	260.00 —
0361	FRT SENSOR BRKT SET	51 11 2 208 723	Original	rec —	120.00 —
0415	L/F GRILLE	51 13 7 203 649	Original	cur —	200.00 —
0416	R/F GRILLE	51 13 7 203 650	Original	cur —	200.00 —
0431	GRILLE BADGE	51 14 7 057 794	Original	12 * —	85.00 x
0561	LEFT HEADLAMP ASSY	63 11 7 343 911	Original	320 —	3,500.00 —
0567	L/INN H-LAMP LED-MOD	63 12 7 262 731	OEM	71X —	477.35x
0577	L/F LED INDICATOR	63 11 7 271 901	OEM	71X —	395.75x
0625	L/F WASHER JET	61 67 7 377 667	Original	800 —	200.00 —
0671	L/GAS DISCHARGE LAMP	63 21 7 217 509	Original	71X —	372.20x
1009	RADIATOR AIR GUIDE	51 74 7 200 787	Original	700 —	480.00 —
1000	FRT SENSOR WIRING	PARKING SENSOR	Original	701 —	550.00 —
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				9,195.30
u: Used parts	Fixed Sundry Parts Price				100.00
	Total				9,295.30

Extras

Code	Description		Price SGD
1001	HEADLAMP ECU PROGRAMMING	2 400	800.00*
	Total Extras		800.00

Final Calculation

	SGD	SGD
Parts	9,195.30	
Fixed Sundry Parts Price	100.00	
Total Parts		9,295.30
Labour Time Base 12 WU/h		
Total 69.0 WU X 42.00 SGD/h	241.50	
Total of Labour		241.50
Total Of Extras		800.00
Paint Work Time Base 12 WU/h		
Labour Cost 40.0 WU X 42.00 SGD/h	140.00	
Material Cost	98.47	
Total Paint Including Material		238.47
Repair Cost Excludes GST		10,575.27
GST (+7.0%)		740.27
Repair Cost Included GST		11,315.54

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.