

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010510/GQCM4**Date:** 31/05/2023**REFERENCE**

Insured/Claimant:	ZHANG QUN	Policy No:	1900018296-01	Claim No:	5197710139SG
Date of Loss:	19/10/2022	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ465K		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK075692
Reg. Date:	20/02/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF48KN006725
Colour:	Blue	Odometer:	7065 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40ZR18	Rear Tyre Size:	245/40ZR18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,573.00	10,188.96	8,384.04	45.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	3,022.00	2,100.00	41.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,695.00	13,210.96	10,484.04	44.25
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	22,095.00	11,610.96	10,484.04	47.45
+ GST 8.00/8.00% (\$\$)	1,767.60	928.88	838.72	47.45
Nett Amount (\$\$)	23,862.60	12,539.84	11,322.76	47.45

INSPECTION

Date of Assignment:	25/10/2022		
Date Inspected:	21/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Broken	254.00 FS	*203.20 FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Missing	72.00 FS	*57.20 FS
7	1		*RADIATOR GRILLE	Not Necessary	1,478.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	151.00 FS	*120.40 FS
9	1		*FRONT BUMPER GUIDE SECTION - RH	Broken	41.00 FS	*32.24 FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
15	1		*FRONT BUMPER BRACKET	Not Necessary	154.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
17	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	531.00 FS	*- FS
18	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
19	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
20	1		*HORN BRACKET - RH	Not Necessary	33.00 FS	*- FS
21	1		*FRONT FENDER - RH	Buckled	861.00 FS	*688.80 FS
22	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	225.00 FS	*- FS
23	1		*FRONT FENDER CLOSING ELEMENT - RH	Broken	81.00 FS	*64.24 FS
24	1		*FRONT FENDER BRACKET - RH	Bent	41.00 FS	*32.72 FS
25	7		*FRONT FENDER RIVET	Necessary	27.00 FS	*21.28 FS
26	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	55.00 FS	*- FS
27	1		*FRONT FENDER BRACE - RH	Broken	132.00 FS	*105.20 FS
28	1		*FRONT WHEEL HOUSING LINER - RH	Torn	262.00 FS	*209.60 FS
29	1		*FRONT WHEEL SPOILER	Distorted	82.00 FS	*65.12 FS
30	1		*FRONT BUMPER SPOILER - RH	Distorted	40.00 FS	*32.00 FS
31	1		*FRONT FENDER LEDGE COVER - RH OUTER	Not Necessary	35.00 FS	*- FS
32	1		*FRONT FENDER LEDGE COVER - RH	Bent	26.00 FS	*20.16 FS
33	1		*HEADLIGHT - RH	Broken	8,294.00 FS	*6,635.20 FS
34	1		*HEADLIGHT HOSE - RH	Not Necessary	42.00 FS	*- FS
35	1		*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
36	1		*LIFT CYLINDER BRACKET	Not Necessary	7.00 FS	*- FS
37	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
38	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	45.00 FS	*- FS
39	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
40	1		*RADIATOR AIR GUIDE - RH INNER	Not Necessary	32.00 FS	*- FS
41	1		*RADIATOR AIR GUIDE - RH OUTER	Not Necessary	14.00 FS	*- FS
42	1		*RADIATOR AIR GUIDE - UPPER CENTER	Not Necessary	19.00 FS	*- FS
43	1		*RADIATOR AIR GUIDE - LH OUTER	Not Necessary	14.00 FS	*- FS
44	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
45	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 18,573.00 10,188.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,122.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >