



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 6279Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR ABSORBER LH	BENT	270.60	270.60
1	REAR ABSORBER SPRING	NOT NECESSARY	231.60	-
1	REAR ABSORBER MOUNTING	NECESSARY	21.80	21.80
1	REAR ABSORBER STOPPER	NOT NECESSARY	24.50	-
1	REAR ABSORBER COVER	NOT NECESSARY	21.80	-
1	KNUCKLE	BENT	316.70	316.70
1	WHEEL HUB BEARING	NECESSARY	367.10	367.10
1	REAR LH (UPPER ARM REAR RH)	BENT	437.50	188.00
1	REAR (TRAILING ARM REAR RH)	BENT	823.60	399.50
	LESS 20% DISCOUNT		-503.04	-312.74
			2,012.16	1,250.96
	<u>SPECIAL NETT ITEMS</u>			
1	TYRE RIM (SN)	CUT	250.00	250.00
			250.00	250.00
	<u>LABOUR</u>			
	TO PANEL BEAT REAR LH DOOR & FENDER & BUMPER .		400.00	400.00
	TO PUTTY & SPRAY PAINT REAR LH DOOR ,FENDER AND BUMPER REAR .		600.00	600.00
	TO REMOVE & REPLACE UNDERCARRIAGE PARTS @ KNUCKLE ,ABSORBER LOWER ARM.		600.00	200.00
	TO PUMP WHEEL BEARING .		120.00	30.00
	TO COMPUTERSE WHEEL ALIGNMENT.		80.00	80.00
			1,800.00	1,310.00
GRAND TOTAL			4,062.16	2,810.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS/AGI22010513/Evy3q2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.