

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: **SKA 6557K**
 Policy No: _____
 Claims No: **C10018089/JY**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Ven: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Val. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: **SJF 62792** Yr Regn: **5/6/08**
 Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Honda Stream** c.c. **1799**
 Colour: **Black** A/C: Insured / Std / Nil / NA
 Sp. Reading: **179336** T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: **RA 61061439**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **215/45R17**
 R: **11**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or: **Westlake**
 Front
 R/Bal. **5** mm R/Bal. **5** mm
 L/Bal. **5** mm L/Bal. **5** mm
 D.O.A. **15/10/22** Xing
 D.O.I. **15/10/22**
 Survey held at **Xing**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear LH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MR-8X
28/11/22	Steve informed LS \$2250 (Red 1812.16, 44%)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2) 28/11/22-typist

Report Format: **TP**

Lump Sum / L.S. (\$) **\$2250**

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@gmail.com

Tel: 6270 3481 Fax: 6278 7522

Steve (LKK)

15/10/22, 3:00 PM

W N

L/S, R/L 11 4 - \$ 4 d/s

Date : 21.10.2022

Address : AUSTIN LUCKY TAN LAN SIONG
BLK 93A TELOK BLANGAH ST.31
#30-151
SINGAPORE 101093

Reference : TP 1328/10/22
Vehicle No : SJF6279Z
Make/Model : HONDA STREAM
Insurance Co. : ETIQA

RE : QUOTATION REPAIRS TO SJF 6279Z FOR THIRD PARTY CLAIMS.

PARTS REQUIRED	QTY	AMT \$
1) REAR ABSORBER LH ?	1	\$ 270.60
2) REAR ABSORBER SPRING X	1	\$ 231.60
3) REAR ABSORBER MOUNTING X	1	\$ 21.80
4) REAR ABSORBER STOPPER X	1	\$ 24.50
5) REAR ABSORBER COVER X ?	1	\$ 21.80
6) KNUCKLE ?	1	\$ 316.70
7) WHEEL HUB BEARING ?	1	\$ 367.10
8) REAR LH LOWER ARM ?	1	\$ 437.50
9) REAR CROSSMEMBER ?	1	\$ 823.60

LIST PRICE TOTAL \$ 2,515.20
LESS DISCOUNT 20% \$ 503.04
LIST PRICE TOTAL AFTER LESS \$ 2,012.16

10) TYRE RIM ✓ CUT \$ 250.00
NETT PRICE TOTAL \$250.00

TOTAL PARTS COST **\$2,262.16**

LABOUR AND MISCELLANEOUS CHARGES

- 1) TO PANEL BEAT REAR LH DOOR & FENDER & BUMPER \$ 400.00 ✓
(5 DAYS)
- 2) TO PUTTY & SPRAY PAINT REAR LH DOOR, FENDER AND BUMPER REAR \$ 600.00 ✓
(3 PANELS)
- 3) TO REMOVE & REPLACE UNDERCARRIDGE PARTS @ KNUCKLE, ABSORBER, LOWER ARM.... \$ 600.00 200
- 4) TO PUMP WHEEL BEARING \$ 120.00 30
- 5) TO COMPUTERISE WHEEL ALIGNMENT \$ 80.00 ✓

LABOUR TOTAL

\$ 1,800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL ESTIMATED REPAIR COST

\$ 3,812.16