

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22010514/Uqy3m4	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	ا	Date:	03/11/2022	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YM 9769S	Veh. Inspected		FBS 7345K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/026448	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		25/10/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA NMAX	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	MH3SG5680MJ079379	Colour		SILVER	
	Odometer	47647 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	110-70-13	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	130-70-13	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSBODY.	STAINED DAMAGES AT THE N/S FRONT PORTION & O/S				
5.	General Information					
	Accident Date	19/10/2022	Inspect Date / T	ime	25/10/2022 (01:25 PM)	
	Survey held at	M 1 MOTORING				
		411 CHANGI ROAD SINGAPORE 419860				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22010514/Uqy3m4

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser