

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22010522/SQY3M4**Date:** 06/04/2023**REFERENCE**

Insured/Claimant: NG YU HUI (HUANG YUHUI) Policy No: DMPCSNW00172422201

Date of Loss: 17/10/2022

Nature of Claim: OD

Claim No: SNM22D207478/C01/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKF5225Z**
 Make & Model: MERCEDES-BENZ E250, 1.8 (A) Engine No: 27186030316999
 Reg. Date: 19/01/2012 (Man. Year: 2011) Chassis No: WDD2074472F139793
 Colour: White Odometer: 192218 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: S\$99,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 ZR19 Rear Tyre Size: 245/35 ZR19
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 5 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,606.34	6,636.73	6,969.61	51.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,230.00	1,570.00	56.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,406.34	7,866.73	8,539.61	52.05
Approved Total (Overridden) (S\$)		6,300.00		
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	15,656.34	5,550.00	10,106.34	64.55
+ GST 8.00/8.00% (S\$)	1,252.51	444.00	808.51	64.55
Nett Amount (S\$)	16,908.85	5,994.00	10,914.85	64.55

INSPECTION

Date of Assignment: 25/10/2022

Date Inspected: 26/10/2022 Inspected At:

Estimated Period of Repair: 5.0 days

GARAGE 13 PTE LTD - KAKI BUKIT (HQ)
8 KAKI BUKIT AVENUE 4, #02-54/55 PREMIER @
KB
SINGAPORE 415875

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2023)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF5225Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,610.00 F	*1,385.00 FL
2	2		*BONNET HINGE	Not Necessary	184.00 F	*- FL
3	1		*BONNET LOGO	Necessary	43.70 F	*43.70 FL
4	1		*FRONT BUMPER	Cracked	1,109.75 F	*1,109.75 FL
5	2		*FRONT BUMPER SIDE BRACKET	Necessary	23.00 F	*23.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	201.25 F	*- FL
7	2		*FRONT BUMPER SPONGE SIDE	Cracked	92.00 F	*92.00 FL
8	1		*FRONT BUMPER FOG LAMP GARNISH 2PIECES	Cracked/Missing (1Piece Only)	110.40 F	*55.20 FL
9	1		*FRONT BUMPER FOG LAMP	O/s Broken	598.00 F	*299.00 FL
10	1		*FRONT BUMPER PARKING SENSOR 6PIECES	Broken (3Pieces Only)	690.00 F	*150.00 FL
11	1		*FRONT BUMPER NOZZLE 2PIECES	Broken (1Piece Only)	253.00 F	*98.00 FL
12	1		*FRONT BUMPER NOZZLE COVER 2PIECES	Missing (1Piece Only)	80.50 F	*40.25 FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*FRONT BUMPER GRILLE	Missing	80.50 F	*80.50 FL
15	1		*HEADLAMP	O/s Cracked	3,795.00 F	*1,630.00 FL
16	1		*HEADLAMP PANEL	O/s Cracked	379.50 F	*148.00 FL
17	1		*FRONT FENDER RH	Buckled	667.00 F	*530.00 FL
18	1		*FRONT FENDER INNER SHIELD - FRONT RH	Cracked	224.25 F	*224.25 FL
19	1		*FRONT FENDER INNER SHIELD - REAR RH	Not Necessary	224.25 F	*- FL
20	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 F	*40.00 FL
21	1		*FRONT RADIATOR GRILLE ASSY	Missing	540.50 F	*540.50 FL
22	1		*INTERCOOLER	Cracked	630.00 F	*630.00 FL
23	1		*ENGINE COVER	Cracked	85.00 F	*85.00 FL
24	1		*FRONT BUMPER UNDER COVER	Cracked	120.00 F	*120.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,831.60	7,374.15
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	737.42
+ Margin on L,N Items 15.00/0.00% (\$\$)	1,774.74	0.00
Total Parts (\$\$)	13,606.34	6,636.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	1,100.00	600.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS	New	100.00	0.00
4	WIRING / BULB CHECKING	New	50.00	0.00
5	REMOVE / REPLACE FRONT BUMPER SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	100.00	30.00
6	CHECK / DIGNOSTIC AND REPROGRAMMING	New	250.00	0.00
Gross Labour Cost (S\$)			2,800.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >