

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/LPC 22010538/UP03

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDM 1052C
at Workshop m/s Zedman 10am.
of

Insured: SJR 8089D

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$120k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

920G
Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SDM 1052C

Yr Regn:

06/06/12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Toyota Alphard c.c 2362

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

233381

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ANH 208207419

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

30/08/22

D.O.I.

28/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 13k.

Called 31-05-2032 LTA & 89817

7/12/22 2/2 & 800 in Bunk william.

Date/Time, File Pass to?

☐
☐

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐
☐
☐
☐

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

) S + RS. SI

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Lonpac Insured's Veh No : SJR8098D

Date of Accident : 30 August 2022

Mr Tan Ha Guan

Date : 31 August 2022

Estimate To Repair SDM1052C - Toyota Alphard 2.4X A
Chassis No : ANH208207419

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper	\$ 1,893.84
02	8 ps	front bumper clips @ \$4.50	\$ 36.00
03	1 pc	front bumper side retainer n/s	\$ 75.00
04	1 pc	n/s front fender	\$ 780.10
05	8 ps	n/s front fender inner cowling clips @ \$4.50	\$ 36.00
			\$ 2,820.94
Less 30 %			\$ 846.28
			\$ 1,974.66
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 60.00
02		To rust-proofing of the affected areas.	\$ 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600.00
04		Putty and spray painting of the affected portion.	\$ 650.00
			\$ 1,390.00
Total			\$ 3,364.66

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: