

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22010542/EPA3Q2**Date:** 06/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000565343
Claimant Vehicle No :	SJG523C	Insured Vehicle No :	SMK9555U
Date of Loss:	21/10/2022	Nature of Claim:	TP
		Claim No:	202222007629

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG523C	Engine No:	R16B21601216
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650GT000939
Reg. Date:	15/03/2017 (Man. Year: 2016)	Odometer:	94439 km
Colour:	Black		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Firestone 4 mm	Rear Left Side:	Firestone 4 mm
Front Right Side:	Firestone 4 mm	Rear Right Side:	Firestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,175.45	1,565.64	609.81	28.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,100.00	8,360.00	3,740.00	30.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,275.45	9,925.64	4,349.81	30.47
+ GST 7.00/7.00% (S\$)	999.28	694.79	304.49	30.47
Nett Amount (S\$)	15,274.73	10,620.43	4,654.30	30.47
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,371.43		

INSPECTION

Date of Assignment:	25/10/2022		
Date Inspected:	02/11/2022	Inspected At:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD Singapore -
Estimated Period of Repair:	8.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2023)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG523C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY.RR.BUMPER	Dented	462.90 FS	*462.90 FS
2	1		*REFLECTOR ASSYR.RR	Not Necessary	14.40 FS	*- FS
3	1		*REFLECTOR ASSYL.RR	Not Necessary	14.40 FS	*- FS
4	1		*GARNISH.RR.BUMPER LOWER	Cut	31.50 FS	*31.50 FS
5	1		*GARNISH.R.RR.BUMPER SIDE	Not Necessary	6.75 FS	*- FS
6	1		*GARNISH.L.RR.BUMPER SIDE	Not Necessary	6.75 FS	*- FS
7	1		*BEAM COMPRR.BUMPER	Deformed	142.57 FS	*142.57 FS
8	1		*SPACERR.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
9	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
10	1		*CLIP BUMPER (7 PCS)	Necessary	12.07 FS	*12.07 FS
11	1		*LID COMP TRUNK	Dented	543.52 FS	*543.52 FS
12	1		*WEATHERSTRIPTRUNK LID	Torn	52.50 FS	*52.50 FS
13	1		*EMBLEM SETRR	Necessary	10.20 FS	*10.20 FS
14	1		*EMBLEMRR	Necessary	9.52 FS	*9.52 FS
15	1		*TAILLIGHT ASSYR	Not Necessary	226.27 FS	*- FS
16	1		*TAILLIGHT ASSYL	Not Necessary	243.52 FS	*- FS
17	1		*PANEL SETRR	Dented	210.52 FS	*210.52 FS
18	1		*LINING ASSYRR PANEL	Not Necessary	37.72 FS	*- FS
19	1		*SUNDRIES	Necessary	110.00 FS	*50.00 FS
20	1		*STIFFENERL.RR.PANEL SIDE	Bent	23.10 FS	*23.10 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,175.45	1,565.64
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	280.00	280.00
2	REMOVE & RENEW REVERSE SENSORS	New	280.00	280.00
3	RESET VEHICLE SMART ENTRY SYSTEM	New	560.00	500.00
4	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	560.00	500.00
5	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	New	560.00	480.00
6	BODY JOINT SEALANT END PANEL	New	120.00	120.00
7	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	5,200.00	3,250.00
8	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	4,160.00	2,600.00
9	BODY UNDERSIDE COATING	New	380.00	350.00
Gross Labour Cost (\$\$)			12,100.00	8,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >