

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22010543/AYA3Q2**Date:** 19/05/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MCV0008340
Claimant Vehicle No :	SKC7084R	Insured Vehicle No :	GBK7200L
Date of Loss:	22/10/2022	Nature of Claim:	TP
		Claim No:	MCV2022D0006620

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC7084R	Engine No:	2ZRA751703
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W805002009
Reg. Date:	23/09/2011 (Man. Year: 2011)	Odometer:	198576 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,395.02	5,569.37	1,825.65	24.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	1,920.00	1,710.00	47.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,025.02	7,489.37	3,535.65	32.07
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	11,025.02	6,000.00	5,025.02	45.58
+ GST 8.00/8.00% (S\$)	882.00	480.00	402.00	45.58
Nett Amount (S\$)	11,907.02	6,480.00	5,427.02	45.58
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,287.45		

INSPECTION

Date of Assignment:	25/10/2022	MG Solution Pte Ltd (HQ)
Date Inspected:	25/10/2022 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC7084R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,355.20 FL	*1,355.20 FL
2	1		*TAIL GATE LOGO	Necessary	80.00 FL	*80.00 FL
3	1		*TAIL GATE EMBLEM VALVE MATIC	Necessary	60.00 FL	*60.00 FL
4	1		*TAIL GATE EMBLEM DELUXE	Necessary	60.00 FL	*60.00 FL
5	1		*TAIL GATE EMBLEM BORNEO MOTOR	Necessary	60.00 FL	*60.00 FL
6	1		*TAIL GATE TOP LOCK	Damaged	468.40 FL	*343.00 FL
7	1		*TAIL GATE LOWER CATCH	Not Necessary	62.00 FL	*- FL
8	2		*TAILGATE LAMP	Cracked	732.40 FL	*732.40 FL
9	1		*TAILGATE INNER BOARD	Cracked	680.50 FL	*485.00 FL
10	1		*TAILGATE WEATHER STRIP	Cut	366.20 FL	*366.20 FL
11	1		*TAILGATE NUMBER PLATE CHROME	Cracked	280.90 FL	*280.90 FL
12	1		*TAILGATE WINDSCREEN MOULDING	Necessary	165.00 FL	*165.00 FL
13	1		*REAR BUMPER	Distorted	688.30 FL	*688.30 FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	144.00 FL	*144.00 FL
15	2		*REAR BUMPER REFLECTOR	Not Necessary	180.00 FL	*- FL
16	1		*REAR BUMPER STAY	N/S Dented	177.40 FL	*88.70 FL
17	1		*TAILLAMP	N/S Cracked	961.00 FL	*409.00 FL
18	1		*REAR FENDER INNER TRIM BELOW	N/S Cracked	1,510.60 FL	*480.00 FL
19	1		*REAR END PANEL	Dented	610.50 FL	*610.50 FL
20	1		*REAR END PANEL TOP GARNISH	Cracked	255.30 FL	*255.30 FL
21	1		*REAR TAILGATE ALTERNATIVE SWITCH	Cracked	189.00 FL	*189.00 FL
22	1		*REAR NUMBER PLATE	Cut	50.00 FS	*50.00 FS
23	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
25	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
26	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
27	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
28	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,666.70	7,282.50
- List Item Discount on L Items 25.00/25.00% (\$)	2,271.68	1,713.13
Total Parts (\$)	7,395.02	5,569.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,400.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	800.00
3	WIRING CHECK	New	150.00	30.00
4	TUFF COAT	New	200.00	60.00
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	New	180.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	180.00	50.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			3,630.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >