



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PD 3399U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b> TO REPLACE ALUMINIUM PLATE FOR THE FRONT DOOR .UNINSTALL DOOR UNIT AND RE ALIGNMENT.} TO REPAIR THE LHS FRONT CORNER DENTED AREAS ,FIRBRE UP AND SAND.} SECA. } LABOUR FOR SPRAY BACK ORIGINAL COLOURS ON ALL REPAIRED BODYWORK.}		2,600.00 - - -	2,440.00 - - -
			2,600.00	2,440.00
<b>GRAND TOTAL</b>			<b>2,600.00</b>	<b>2,440.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,440.00</b>

Report Ref No. CC4/ASM22010546/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.