

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010558/TNY3Q2**Date:** 11/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00216792100

Claimant Vehicle No : SND7752E **Insured Vehicle No :** SMU4180Y

Date of Loss: 22/10/2022 Nature of Claim: TP Claim No: SNM22D207588/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND7752E**

Make & Model: TOYOTA COROLLA ALTIS, 1.8 E HYBRID ELEGANCE (2WD) (A) Engine No: 2ZRY791728

Reg. Date: 25/01/2022 (Man. Year: 2021) Chassis No: MR2BZ3BE300008725

Colour: White Odometer: 50974 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,311.00	1,675.47	7,635.53	82.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,420.00	2,180.00	60.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,911.00	3,095.47	9,815.53	76.02
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	12,911.00	2,450.00	10,461.00	81.02
+ GST 8.00/8.00% (S\$)	1,032.88	196.00	836.88	81.02
Nett Amount (S\$)	13,943.88	2,646.00	11,297.88	81.02

INSPECTION

Date of Assignment: 26/10/2022

Date Inspected: 26/10/2022 Inspected At: My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
60 Jalan Lam Huat, Carros Centre #05-21
Singapore 737869

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.8 E HYBRID ELEGANCE (2WD) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND7752E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,125.00 FL	*933.30 FL
2	1		*BOOTLID INNER TRIM	Not Necessary	359.00 FL	*- FL
3	1		*BOOTLID TOP LOCK	Not Necessary	398.00 FL	*- FL
4	1		*BOOTLID TOP LOCK COVER	Cut	68.00 FL	*68.00 FL
5	1		*BOOTLID WEATHERSTRIP	Twisted	220.00 FL	*220.00 FL
6	1		*BOOTLID LOGO	Necessary	74.00 FL	*74.00 FL
7	1		*BOOTLID EMBLEM ALTIS	Necessary	65.00 FL	*65.00 FL
8	1		*BOOTLID SENSOR	Not Necessary	312.00 FL	*- FL
9	1		*BOOTLID EMBLEM COROLLA	Necessary	65.00 FL	*65.00 FL
10	2		*TAILAMP C/W CHROME	Not Necessary	1,224.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	698.00 FL	*542.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Not Necessary	224.00 FL	*- FL
13	2		*REAR BUMPER BRACKET	Not Necessary	326.00 FL	*- FL
14	2		*REAR BUMPER SENSOR	Not Working	571.50 FS	*200.00 FS
15	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	587.00 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Not Necessary	395.00 FL	*- FL
17	2		*REAR BUMPER REFLECTOR	Not Necessary	224.00 FL	*- FL
18	1		*REAR BUMPER UNDERCOVER	Not Necessary	315.00 FL	*- FL
19	2		*REAR FENDER COWLING	Not Necessary	716.00 FL	*- FL
20	2		*REAR FENDER INNER TRIM	Not Necessary	796.00 FL	*- FL
21	1		*REAR END PANEL	Repair	695.00 FL	*- FL
22	1		*END PANEL TOP GARNISH	Not Necessary	278.00 FL	*- FL
23	1		*REAR FLOOR PANEL	Not Necessary	1,025.00 FL	*- FL
24	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	357.00 FL	*- FL
25	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
26	1		*BOOTLID INSULATOR CLIPS	Not Necessary	30.00 FS	*- FS
27	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
30	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	150.00 FS	*- FS
31	1		*REVERSE CAMERA	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,947.50	2,167.30
- List Item Discount on L Items 25.00/25.00% (S\$)	2,636.50	491.83
Total Parts (S\$)	9,311.00	1,675.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	700.00
2	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	600.00
3	REMOVE AND REFIT UPHOLSTERY SEAT	New	350.00	0.00
4	REMOVE AND REFIR REAR BOOTLID MECHANISM	New	100.00	60.00
5	REAR CHASSIS ALIGNMENT	New	200.00	0.00
6	TO CHECK ELECTRICAL WIRING	New	100.00	30.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	50.00	30.00
Gross Labour Cost (\$\$)			3,600.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >