

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22010561/KPA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210142110
Claimant Vehicle No : SHC5276C **Insured Vehicle No :** SLU5951U
 Date of Loss: 20/10/2022 Nature of Claim: TP Claim No: 7287163921SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5276C**
 Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2H43137
 Reg. Date: 15/01/2021 (Man. Year: 2020) Chassis No: JTDKB3FU203093343
 Colour: Metallic Pearl White/Red Odometer: 134455 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: LANVIGATOR 8 mm Rear Left Side: Firenza 9 mm
 Front Right Side: LANVIGATOR 8 mm Rear Right Side: Firenza 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,998.07	2,250.95	1,747.12	43.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	920.00	4,180.00	81.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,098.07	3,170.95	5,927.12	65.15
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 21/10/2022
 Date Inspected: 21/10/2022 Inspected At: Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FRONT DOOR ,RH	Bent	1,300.70 FL	*1,300.70 FL
2	1		*FRAME SUB-ASSY ,FRONT DOOR OUTSIDE HANDLE RH	Serviceable	193.50 FL	*- FL
3	1		*HANDLE ASSY ,FRONT DOOR ,OUTSIDE RH	Serviceable	390.60 FL	*- FL
4	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,RH	Serviceable	926.00 FL	*- FL
5	1		*WEATHERSTRIP ,FRONT DOOR OPENING TRIM ,RH	Serviceable	321.10 FL	*- FL
6	1		*HINGE ASSY ,FRONT DOOR ,LOWER RH	Distorted	110.60 FL	*110.60 FL
7	1		*HINGE ASSY ,FRONT DOOR ,UPPER RH	Distorted	97.50 FL	*97.50 FL
8	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,RH	Serviceable	238.30 FL	*- FL
9	1		*TAPE, BLACK OUT,NO.2 FRT RH	Necessary	43.50 FL	*43.50 FL
10	1		*TAPE, BLACK OUT,NO.1 FRT RH	Necessary	13.30 FL	*13.30 FL
11	1		*TAPE, BLACK OUT,NO.3 FRT RH	Necessary	26.30 FL	*26.30 FL
12	1		*FENDER SUB-ASSY ,FRONT RH	Bent	977.80 FL	*977.80 FL
13	1		*EMBLEM ,SIDE PANEL, RH	Necessary	54.60 FL	*54.60 FL
14	1		*LINER ,FRONT FENDER ,LH	Distorted	210.30 FL	*210.30 FL
15	1		*FRT FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS
16	1		*DOOR STICKER TRANS-CAB	Necessary	100.00 FS	*60.00 FS
17	1		*DOOR TRIM CLIP	Not Necessary	75.00 FS	*- FS
18	1		*DOOR WEATHERSTRIP CLIP	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)						5,224.10 2,959.60
- List Item Discount on L Items 25.00/25.00% (S\$)						1,226.03 708.65
Total Parts (S\$)						3,998.07 2,250.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	60.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	400.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	440.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			5,100.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >