

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010567/DNY3Q2**Date:** 22/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00097672101

**Claimant Vehicle
No :** SMY7307J**Insured Vehicle
No :** GBG5530T

Date of Loss: 17/01/2022

Nature of Claim: TP

Claim
No: SNM22D202458/C02/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMY7307J**

Make & Model: MERCEDES-BENZ GLC300E, 2.0 4MATIC (A)

Engine No: 26492080093658

Reg. Date: 23/03/2021 (Man. Year: 2020)

Chassis No: W1N2533842F868021

Colour: Red

Odometer: 27226 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45 R20

Rear Tyre Size: 255/45 R20

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	71,558.16	2,330.48	69,227.68	96.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,600.00	600.00	6,000.00	90.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	78,158.16	2,930.48	75,227.68	96.25
Approved Total (Overridden) (\$\$)		2,300.00		
(\$\$)	78,158.16	2,300.00	75,858.16	97.06
+ GST 7.00/7.00% (\$\$)	5,471.07	161.00	5,310.07	97.06
Nett Amount (\$\$)	83,629.23	2,461.00	81,168.23	97.06

INSPECTION

Date of Assignment: 26/10/2022

Date Inspected: 27/10/2022 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Nov 2022)

Parts: M1-SUV MERCEDES-BENZ GLC300E 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMY7307J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	4,259.10 FL	*2,589.42 FL
2	1		*BONNET INSULATOR	Not Necessary	1,049.80 FL	*- FL
3	1		*BONNET SEAL	Not Necessary	210.00 FL	*- FL
4	1		*BONNET LOGO	Not Necessary	149.00 FL	*- FL
5	2		*BONNET HINGE LH/RH	Not Necessary	438.00 FL	*- FL
6	2		*HEAD LAMP LH/RH	Not Necessary	16,996.00 FL	*- FL
7	2		*HEAD LAMP LOWER BRACKET LH/RH	Not Necessary	796.00 FL	*- FL
8	2		*HEAD LAMP ECU LH/RH	Not Necessary	5,960.00 FL	*- FL
9	1		*HEAD LAMP WIRE HARNESS	Not Necessary	4,189.00 FL	*- FL
10	1		*FRONT GRILLE	Not Necessary	1,419.20 FL	*- FL
11	1		*FRONT GRILLE GARNISH	Not Necessary	410.00 FL	*- FL
12	1		*SET FRONT GRILLE CHROME	Not Necessary	890.00 FL	*- FL
13	1		*FRONT GRILLE LOGO	Not Necessary	1,298.00 FL	*- FL
14	1		*FRONT RADAR ASSY	Not Necessary	6,198.00 FL	*- FL
15	1		*FRONT RADAR GARNISH	Not Necessary	398.00 FL	*- FL
16	1		*FRONT BUMPER	Not Necessary	2,198.00 FL	*- FL
17	2		*FRONT BUMPER SIDE GARNISH LH/RH	Not Necessary	820.00 FL	*- FL
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	891.00 FL	*- FL
19	1		*FRONT BUMPER LOWER CENTER CHROME	Not Necessary	598.00 FL	*- FL
20	2		*FRONT BUMPER LOWER SIDE CHROME LH/RH	Not Necessary	820.00 FL	*- FL
21	1		*FRONT BUMPER UNDER COVER	Not Necessary	510.00 FL	*- FL
22	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	638.00 FL	*- FL
23	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	101.00 FL	*- FL
24	1		*FRONT BUMPER NO PLATE HOLDER	Not Necessary	231.00 FL	*- FL
25	4		*FRONT BUMPER SENSOR	Not Necessary	1,400.00 FL	*- FL
26	1		*SET FRONT BUMPER SENSOR HOLDER	Not Necessary	80.00 FL	*- FL
27	1		*FRONT BUMPER SENSOR WIRE HARNESS	Not Necessary	3,198.70 FL	*- FL
28	1		*FRONT BUMPER SPONGE	Not Necessary	412.00 FL	*- FL
29	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,984.50 FL	*- FL
30	1		*FRONT SUPPORT PANEL	Not Necessary	2,894.50 FL	*- FL
31	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	410.90 FL	*- FL
32	2		*FRONT SUPPORT PANEL SIDE GARNISH LH/RH	Not Necessary	758.20 FL	*- FL
33	1		*FRONT INTER -COOLER ASSY	Not Necessary	3,149.00 FL	*- FL
34	1		*A/C CONDENSOR ASSY	Not Necessary	2,398.00 FL	*- FL
35	1		*A/C CONDENSOR DISCHARGE HOSE	Not Necessary	1,094.00 FL	*- FL
36	1		*A/C CONDENSOR SUCTION HOSE	Not Necessary	481.00 FL	*- FL
37	1		*RADIATOR ASSY	Not Necessary	2,784.50 FL	*- FL
38	1		*RADIATOR TOP HOSE	Not Necessary	103.00 FL	*- FL
39	1		*RADIATOR BOTTOM HOSE	Not Necessary	129.00 FL	*- FL
40	1		*RADIATOR FAN ASSY COMPLETE	Not Necessary	1,698.00 FL	*- FL
41	2		*FRONT FENDER LH/RH	Not Necessary	3,780.00 FL	*- FL
42	2		*FRONT FENDER INNER SHIELD LH/RH	Not Necessary	620.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
47	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*FRONT BUMPER SIDE GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*COOLANT	Not Necessary	100.00 FS	*- FS
50	1		*FRONT NO PLATE & CASING	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					79,442.40	2,589.42
- List Item Discount on L Items 10.00/10.00% (S\$)					7,884.24	258.94
Total Parts (S\$)					71,558.16	2,330.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,400.00	300.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	2,400.00	300.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR INTER -COOLER TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
7	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
8	TO RNR FRONT PARKING SENSOR TO FACILITATE REPAIRS	New	100.00	0.00
9	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			6,600.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >