



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                            |  |  |  |            |
|--|--|--|--|------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN:WINNIE HO |  |  | Ref: CC4/ASM22010576/Upa3q2<br>Date: 16/01/2023<br>Code: ASM |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |  |  |            |
|  | Insured Veh.   | SLE 8210P  | Veh. Inspected   | SJR 7854T  |
|  | Policy No.   | P2288717   | Coverage (\$)  | 0.00       |
|  | Claim No.  | S2M04DD8   | Excess (\$)  | 0.00       |
|  | Assign From  |  | Assign Date  | 25/10/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |  |  |            |
|  | Make & Model   | SUZUKI SWIFT (A)   | c.c  | 1328       |
|  | Engine No.   | HIDDEN   | Year of Reg.   | 2009       |
|  | Chassis No.  | JSAEZC11S00550654  | Colour   | BLUE       |
|  | Odometer   | 174701 KM  | Steering   | IN ORDER   |
|  | Brakes   | IN ORDER   | Modification   | NIL        |
|  | General  | GOOD   |  |            |
| <b>3. Conditions of Tyres</b>  |  |  |  |            |
|  |  | Size   | Make   | Balance    |
|  | R/H Front Tyre   | 175/70 R14   | BRIDGESTONE  | 6 mm       |
|  | L/H Front Tyre   | 175/70 R14   | BRIDGESTONE  | 6 mm       |
|  | R/H Rear Tyre  | 175/70 R14   | KAPSEN   | 6 mm       |
|  | L/H Rear Tyre  | 175/70 R14   | KAPSEN   | 6 mm       |
| <b>4. Description of Damages</b>   |  |  |  |            |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br><br>DAMAGES SEE DETAILS.   |  |  |            |
| <b>5. General Information</b>  |  |  |  |            |
|  | Accident Date  | 22/10/2022   | Inspection Date  | 26/10/2022 |
|  | Survey held at   | T K LEE AUTOMOTIVE PTE LTD<br>NO. 1 KAKI BUKIT AVE 6<br>#02-47 AUTOBAY<br>SINGAPORE 417883 |  |            |
| <b>5a. Remarks</b>   |  |  |  |            |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |  |            |
| <b>5b. Estimate Days of Repair</b>   |  |  |  |            |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 6 Working Days   |            |