

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CC3/AIS22010586/EVCQ2**Date:** 01/12/2022**REFERENCE**

Insured/Claimant:	NG SAN SAN	Policy No:	SP2000706520	
Date of Loss:	22/10/2022	Nature of Claim:	OD	Claim No: 202222007633

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL1749K	Engine No:	CZC162274
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A)	Chassis No:	WVWZZZAUZH121987
Reg. Date:	26/01/2017 (Man. Year: 2016)	Odometer:	107575 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,120.04	7,581.79	3,538.25	31.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,260.00	9,800.00	2,460.00	20.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,380.04	17,381.79	5,998.25	25.66
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	22,780.04	16,781.79	5,998.25	26.33
+ GST 7.00/7.00% (S\$)	1,594.60	1,174.73	419.87	26.33
Nett Amount (S\$)	24,374.64	17,956.52	6,418.12	26.33

INSPECTION

Date of Assignment:	26/10/2022	
Date Inspected:	26/10/2022	Inspected At: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934
Estimated Period of Repair:	12.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2022)
Parts:	144	VOLKSWAGEN GOLF 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL1749K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*THREE -POINT AUTOMATIC SEA SEAT BELT LH	Jammed	759.34 FS	*759.34 FS
2	1		*THREE-POINT AUTOMATIC SEA SEAT BELT RH	Jammed	759.34 FS	*759.34 FS
3	2		*BOLT WITH POLYGON SOCKET	Necessary	10.38 FS	*10.38 FS
4	1		*SOCKET HD .SCREW WITH POL (2 PCS)	Necessary	10.57 FS	*10.57 FS
5	1		*SOCKET HD .SCREW WITH POL (2 PCS)	Necessary	9.55 FS	*9.55 FS
6	2		*SEAT BELT HEIGHT ADJUSTER	Necessary	178.56 FS	*178.56 FS
7	2		*BOLT	Necessary	6.26 FS	*6.26 FS
8	1		*REAR TRUNK LID	Dented	1,836.06 FS	*1,836.06 FS
9	1		*1K WINDOW ADHESIVE (2 PCS)	Necessary	74.07 FS	*74.07 FS
10	1		*ALL PURPOSE CLEANER	Necessary	74.07 FS	*74.07 FS
11	1		*RPIMER	Necessary	21.79 FS	*21.79 FS
12	1		*ACTIVATOR	Necessary	18.91 FS	*18.91 FS
13	1		*APPLICATOR (2 PCS)	Necessary	16.07 FS	*16.07 FS
14	1		*HOOD LATCH SATIN BLACK BOOT LID LOCK	Bent	192.16 FS	*192.16 FS
15	1		*GASKET BOOT LID WEATHERSTRIP	Crushed	215.58 FS	*215.58 FS
16	1		*OPER MECHAN WITH MICRO SW	Not Necessary	1,517.60 FS	*- FS
17	1		*WATER DRAIN HOSE	Necessary	6.87 FS	*6.87 FS
18	1		*TRIM PANEL FOR HATCH GATE BOOT LID TRIM COVER	Cut	136.02 FS	*136.02 FS
19	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -GOLF	Necessary	64.63 FS	*64.63 FS
20	1		*INSCRIPTION BRIGHT CHROME NAME PLATE 230 TSI	Necessary	58.40 FS	*58.40 FS
21	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRAKE LIGHT	Necessary	131.82 FS	*131.82 FS
22	1		*TAILLIGHT LHS TAILLIGHT INNER	Not Necessary	228.33 FS	*- FS
23	1		*TAILLIGHT RHS TAILLIGHT INNER	Not Necessary	228.33 FS	*- FS
24	1		*COVER FOR BUMPER PRIMED	Dented	1,020.60 FS	*1,020.60 FS
25	1		*SET SENSOR BRACKET PRI	Necessary	18.52 FS	*18.52 FS
26	2		*SENSOR BRACKET	Necessary	24.36 FS	*24.36 FS
27	1		*SENSOR BRACKET	Necessary	12.18 FS	*12.18 FS
28	1		*SENSOR BRACKET	Necessary	12.18 FS	*12.18 FS
29	2		*SENSOR PRIMED	Not Necessary	273.86 FS	*- FS
30	2		*SEAL RING SATIN BLACK	Necessary	2.10 FS	*2.10 FS
31	1		*2K -PLASTIC ADHESIVE	Necessary	61.88 FS	*61.88 FS
32	1		*BONDING AGENT FOR PLASTIC	Necessary	49.57 FS	*49.57 FS
33	1		*REAR DIFFUSOR SATIN BLACK	Cut	260.20 FS	*260.20 FS
34	4		*RIVET	Necessary	3.80 FS	*3.80 FS
35	1		*BUMPER REINFORCEMENT	Dented	540.60 FS	*540.60 FS
36	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Broken	52.69 FS	*52.69 FS
37	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Broken	31.20 FS	*31.20 FS
38	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Broken	31.20 FS	*31.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	31.20 FS	*- FS
40	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	31.20 FS	*- FS
41	2		*LICENSE PLATE LIGHT	Not Necessary	63.89 FS	*- FS
42	2		*FLAT CONTACT HOUSING WITH NUMBER PLATE LIGHT WIRE HOUSING	Not Necessary	17.84 FS	*- FS
43	1		*REFLECTOR LH	Not Necessary	58.33 FS	*- FS
44	1		*REFLECTOR RH	Not Necessary	58.33 FS	*- FS
45	1		*REAR APRON REAR END PANEL INNER	Not Necessary	595.79 FS	*- FS
46	1		*BRACKET FOR BUMPER	Not Necessary	10.61 FS	*- FS
47	1		*END PLATE END PANEL OUTER	Dented	152.75 FS	*152.75 FS
48	1		*ZINC SPRAY	Necessary	52.46 FS	*52.46 FS
49	1		*2K-BODY ADHESIVE	Necessary	338.05 FS	*338.05 FS
50	1		*SEALANT CAN BE SPRAYED	Necessary	48.08 FS	*48.08 FS
51	1		*SPEED NUT (5 PCS)	Necessary	6.48 FS	*6.48 FS
52	1		*WELD STUD (8 PCS)	Necessary	6.57 FS	*6.57 FS
53	1		*COVER FOR LOCK CARRIER TI END PANEL TRIM COVER	Crushed	101.89 FS	*101.89 FS
54	1		*CARGO PLATFORM BLACK SPARE WHEEL COVER	Not Necessary	319.20 FS	*- FS
55	1		*MOUNTING TITANIUM BLACK SPARE WHEEL COVER BRACKET LH	Not Necessary	43.11 FS	*- FS
56	1		*MOUNTING TITANIUM BLACK SPARE WHEEL COVER BRACKET RH	Not Necessary	43.11 FS	*- FS
57	1		*BOLT FOR SPARE WHEEL MOON	Not Necessary	17.52 FS	*- FS
58	1		*HEAT SHIELD FOR EXHAUST M	Bent	118.48 FS	*118.48 FS
59	1		*FLOOR PAN INSULATOR	Necessary	53.92 FS	*53.92 FS
60	2		*PLUG	Necessary	1.58 FS	*1.58 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **11,120.04** **7,581.79**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	4,480.00	4,200.00
2	SPRAY PAINT	New	4,240.00	3,180.00
3	R&R REAR W/SCREEN	New	560.00	560.00
4	TRANSFER BOOT LID MECHANISM	New	560.00	280.00
5	R&R REAR LUGGAGE TRIM	New	560.00	280.00
6	R&R REAR EXHAUST PIPE	New	560.00	280.00
7	REAR WATER LEAK TEST	New	100.00	100.00
8	REAR NUMBER PLATE	New	80.00	80.00
9	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	200.00	200.00
10	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
11	R&R FRT SEAT BELT	New	560.00	280.00
Gross Labour Cost (\$\$)			12,260.00	9,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >