

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAI	NCE BHD	Ref:	CS3/LPC22010592/Eqcm4	
	300 BEACH ROAD #17-04/07 THE CO) NCOURSESINGAPORE 199555	Date:	07/11/2022	
			Code	: LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XD 2574S	Veh. Inspected	XD 2756J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	22/22/22/VC05/026461	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	26/10/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FP51	c.c	12882	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	FP51JDA00616	Colour	BLUE	
	Odometer	230721 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	295/80 R22.5	GOODYEAR	4 mm	
	L/H Front Tyre	295/80 R22.5	GOODYEAR	4 mm	
	R/H Rear Tyre	295/80 R22.5	GOODYEAR	4 mm	
	L/H Rear Tyre	295/80 R22.5	GOODYEAR	4 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.				
5.	General Information				
	Accident Date	25/10/2022	Inspect Date / Time	26/10/2022 (04:25 PM)	
	Survey held at	REDANTS ENGINEERING PTE	LTD		
		10 BUROH STREET #04-26/29 WEST CONNECT BUILDING SINGAPORE 627564			
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22010592/Eqcm4

Inspected By

CHEN TSUE YEE

Automotive Assessor

HEN ISUE TEE

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser