

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010595/AVCQ2**Date:** 22/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00257602106

**Claimant Vehicle
No :** SGW9829M**Insured
Vehicle No :** SKX4253D

Date of Loss: 24/10/2022

Nature of Claim: TP

Claim
No: SNM22D207629/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SGW9829M**Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL
LAMP (A)

Engine No: 4A92CP5276

Reg. Date: 17/07/2017 (Man. Year: 2017)

Chassis No: JMYSRCY1AGU006869

Colour: Red

Odometer: 233658 km

Engine Capacity: 1590 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,425.59	4,615.59	2,810.00	37.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,360.00	900.00	39.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,685.59	5,975.59	3,710.00	38.30
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	9,685.59	4,700.00	4,985.59	51.47
+ GST 7.00/7.00% (S\$)	677.99	329.00	348.99	51.47
Nett Amount (S\$)	10,363.58	5,029.00	5,334.58	51.47

INSPECTION

Date of Assignment: 27/10/2022

Date Inspected: 26/10/2022 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2022)
Parts:	143	MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGW9829M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Not Necessary	809.00 FL	*- FL
2	2	*FRONT BONNET HINGES L/R	Not Necessary	110.00 FL	*- FL
3	1	*FRONT BONNET MECHANISM LOCK	Not Necessary	50.00 FL	*- FL
4	1	*FRONT BUMPER	Deformed	858.00 FL	*858.00 FL
5	1	*FRONT BUMPER FOGLAMP GARNISH RH	Cut	85.00 FL	*85.00 FL
6	1	*FRONT BUMPER FOGLAMP RH	Cracked	426.00 FL	*426.00 FL
7	1	*FRONT BUMPER LED LAMP RH	Cracked	586.00 FL	*586.00 FL
8	1	*FRONT BUMPER LOWER GRILLE	Cracked	168.00 FL	*168.00 FL
9	2	*FRONT BUMPER LOWER GRILLE COVER L/R	Not Necessary	24.00 FL	*- FL
10	1	*FRONT BUMPER LOWER GRILLE OUTER CHROME MOULDING	Cracked	221.00 FL	*221.00 FL
11	1	*FRONT BUMPER REINFORCEMENT	Dented	390.00 FL	*390.00 FL
12	1	*FRONT BUMPER RH ANS STANLEY MODULE	Cracked	502.10 FL	*502.10 FL
13	10	*FRONT BUMPER RIVET	Necessary	60.00 FL	*60.00 FL
14	2	*FRONT BUMPER SIDE BRACKET L/R	Not Necessary	32.00 FL	*- FL
15	1	*FRONT BUMPER SIDE RETAINER L/R	O/S Damaged	36.00 FL	*18.00 FL
16	1	*FRONT BUMPER TOP BRACKET	Not Necessary	167.00 FL	*- FL
17	1	*FRONT BUMPER UNDER COVER	Not Necessary	156.00 FL	*- FL
18	1	*FRONT FENDER INNER SHIELD RH	Torn	102.00 FL	*102.00 FL
19	1	*FRONT HEADLAMP L/R	O/S Cracked	1,396.00 FL	*698.00 FL
20	1	*FRONT FENDER RH	Buckled	588.00 FL	*588.00 FL
21	1	*FRONT GRILLE	Cracked	254.00 FL	*254.00 FL
22	1	*FRONT GRILLE EMBLEM	Necessary	48.00 FL	*48.00 FL
23	2	*FRONT HEADLAMP CLIPS L/R	Necessary	12.00 FL	*6.00 FL
24	2	*FRONT HEADLAMP TOP PANEL L/R	Not Necessary	156.00 FL	*- FL
25	1	*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	63.00 FL	*- FL
26	1	*FRONT SUPPORT SIDE PANEL RH	Not Necessary	155.00 FL	*- FL
27	1	*FRONT SUPPORT TOP PANEL	Not Necessary	267.00 FL	*- FL
28	1	*FRONT WASHER TANK	Deformed	85.00 FL	*85.00 FL
29	1	*FRONT WASHER TANK MOTOR	Not Necessary	139.00 FL	*- FL
30	1	*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
31	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
32	1	*FRONT BUMPER NUMBER PLATE	Not Necessary	25.00 FS	*- FS
33	1	*FRONT BUMPER NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
34	1	*SET FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	50.00 FS	*- FS
35	1	*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,220.10	5,125.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	794.51	509.51
Total Parts (\$\$)	7,425.59	4,615.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG ,HEADLAMP FOCUSING (TO FR)	New	60.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,100.00	800.00
3	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	30.00
Gross Labour Cost (\$\$)			2,260.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >