

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22010599/KYA3Q2**Date:** 25/05/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MPC0009794
Claimant Vehicle No : SMA6128S **Insured Vehicle No :** SKL5682E
 Date of Loss: 25/10/2022 Nature of Claim: TP Claim No: MPC2022D0006705

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA6128S**
 Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B5462812
 Reg. Date: 14/06/2018 (Man. Year: 2018) Chassis No: GK81202439
 Colour: Metallic Red Odometer: 79070 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,575.30	4,644.60	1,930.70	29.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,610.00	1,110.00	40.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,295.30	6,254.60	3,040.70	32.71
+ GST 8.00/8.00% (S\$)	743.62	500.37	243.25	32.71
Nett Amount (S\$)	10,038.92	6,754.97	3,283.95	32.71
+ Car Rental (9.0 x S\$100.00/day + 8.00% GST) (S\$)		972.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,728.97		

INSPECTION

Date of Assignment: 26/10/2022
 Date Inspected: 27/10/2022 Inspected At: Optima Werkz Pte Ltd (HQ)
 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
 Autopoint
 Singapore 568047
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Feb 2023)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA6128S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE (WCP)	Bent	600.00 F	*600.00 F
2	1		*REAR TAILGATE WINDSCREEN MOULDING (WCP)	Necessary	40.00 F	*40.00 F
3	1		*REAR TAILGATE LOGO EMBLEM (WCP)	Necessary	24.00 F	*24.00 F
4	1		*REAR TAILGATE SHUTTLE EMBLEM (WCP)	Necessary	34.00 F	*34.00 F
5	1		*REAR TAILGATE LAMP LH (WCP)	Mtg Cracked	225.00 F	*225.00 F
6	1		*REAR TAILGATE LAMP RH (WCP)	Mtg Cracked	225.00 F	*225.00 F
7	1		*REAR TAILGATE OUTER CHROME GARNISH (WCP)	Serviceable	265.00 F	*- F
8	1		*REAR TAILGATE MECHANISM LOCK (WCP)	Jammed	115.00 F	*115.00 F
9	1		*REAR TAILGATE INNER HANDLE COVER (WCP)	Serviceable	18.00 F	*- F
10	1		*REAR TAILGATE INNER TRIM BOARD (WCP)	Mtg Cracked	165.00 F	*165.00 F
11	1		*REAR TAILGATE WEATHERSTRIP (WCP)	Dented/Distorted	78.00 F	*78.00 F
12	1		*REAR TAIL LAMP LH (WCP)	Cut	255.00 F	*255.00 F
13	1		*REAR TAIL LAMP RH (WCP)	Cut	255.00 F	*255.00 F
14	1		*REAR TAIL LAMP INNER PANEL LH (WCP)	Repair	68.00 F	*- F
15	1		*REAR TAIL LAMP INNER PANEL RH (WCP)	Bent	68.00 F	*68.00 F
16	1		*REAR BUMPER (WCP)	Bent	580.00 F	*580.00 F
17	1		*REAR BUMPER SIDE RETAINER LH (WCP)	Serviceable	18.00 F	*- F
18	1		*REAR BUMPER SIDE RETAINER RH (WCP)	Serviceable	18.00 F	*- F
19	1		*REAR BUMPER SIDE GARNISH LH (WCP)	Serviceable	22.00 F	*- F
20	1		*REAR BUMPER SIDE GARNISH RH (WCP)	Serviceable	22.00 F	*- F
21	1		*REAR BUMPER REFLECTOR LH (WCP)	Cracked	32.00 F	*32.00 F
22	1		*REAR BUMPER REFLECTOR RH (WCP)	Serviceable	32.00 F	*- F
23	1		*REAR BUMPER TOWING COVER (WCP)	Serviceable	14.00 F	*- F
24	1		*REAR BUMPER INNER BUZZER (WCP)	Serviceable	50.00 F	*- F
25	1		*REAR END PANEL (WCP)	Bent	310.00 F	*310.00 F
26	1		*REAR END PANEL INNER TOP GARNISH (WCP)	Dented	85.00 F	*85.00 F
27	1		*REAR FLOOR PANEL (WCP)	Repair	640.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR FLOOR PANEL TOOLBOX TRAY (WCP)	Dented	135.00 F	*135.00 F
29	1		*REAR FLOOR PANEL TOP CARD BOARD (WCP)	Serviceable	320.00 F	*- F
30	1		*REAR FENDER INNER TRIM BOARD LH (WCP)	Deformed	255.00 F	*255.00 F
31	1		*REAR FENDER INNER TRIM BOARD RH (WCP)	Deformed	255.00 F	*255.00 F
32	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*REAR NUMBER PLATE WITH HOLDER	Dented	50.00 FS	*45.00 FS
34	1		*REAR TAILGATE INNER TRIM BAORD CLIPS	Necessary	30.00 FS	*30.00 FS
35	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
36	1		*REAR BUMPER REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
37	1		*REAR END PANEL JOINT SEALANT	Necessary	100.00 FS	*30.00 FS
38	1		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
39	1		*REAR FLOOR PANEL INSULATOR MAT	Not Necessary	80.00 FS	*- FS
40	1		*REAR FENDER INNER TRIM BOARD CLIPS LH	Necessary	30.00 FS	*30.00 FS
41	1		*REAR FENDER INNER TRIM BOARD CLIPS RH	Necessary	30.00 FS	*30.00 FS
42	1		*REAR TAILGATE OUTER CHROME MOULDING LOWER	Bent	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)				6,053.00	4,271.00
+ Margin on L,N Items 10.00/10.00% (S\$)				522.30	373.60
Total Parts (S\$)				6,575.30	4,644.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX & READJUST AT ACCIDENT AREAS	New	1,000.00	700.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	1,000.00	600.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR	New	100.00	50.00
4	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS & ETC	New	120.00	120.00
5	LABOUR CHARGES TO REMOVE & REFIX REAR EXHAUST SILENCER BOX & ETC	New	120.00	0.00
6	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
8	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	60.00
9	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	80.00	0.00
Gross Labour Cost (S\$)			2,720.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >