

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22010610/AQCM4**Date:** 01/08/2023**REFERENCE**

Insured/Claimant:	CHAN PEK SIAN DIANA	Policy No:	7210114464	
Date of Loss:	14/10/2022	Nature of Claim:	OD	Claim No: 9453723201SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJU9895X</b>		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC48856
Reg. Date:	29/09/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF37M1153300
Colour:	Green	Odometer:	25452 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,851.00	10,887.68	4,963.32	31.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,812.00	8,212.00	5,600.00	40.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>29,663.00</b>	<b>19,099.68</b>	<b>10,563.32</b>	<b>35.61</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	28,863.00	18,299.68	10,563.32	36.60
<b>+ GST 8.00/8.00% (S\$)</b>	2,309.04	1,463.97	845.07	36.60
<b>Nett Amount (S\$)</b>	<b>31,172.04</b>	<b>19,763.65</b>	<b>11,408.39</b>	<b>36.60</b>

**INSPECTION**

Date of Assignment:	27/10/2022	
Date Inspected:	25/10/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days	

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,738.00 FS	*1,390.40 FS
2	1		*REAR BUMPER SPOILER	Deformed	510.00 FS	*408.00 FS
3	1		*REAR BUMPER GRILLE - RH	Deformed	170.00 FS	*135.60 FS
4	1		*REAR PARKING AID SENSOR SUPPORT - RH	Damaged	28.00 FS	*22.08 FS
5	1		*REAR BUMPER ADAPTER - RH	Not Necessary	95.00 FS	*- FS
6	1		*REAR BUMPER BRACKET	Not Necessary	53.00 FS	*- FS
7	1		*REAR BUMPER REFLECTOR - RH	Cracked	46.00 FS	*36.48 FS
8	1		*REAR OUTER TAIL LIGHT - RH	Cracked	1,030.00 FS	*824.00 FS
9	1		*REAR OUTER TAIL LIGHT TRIM - RH	Cracked	34.00 FS	*26.48 FS
10	1		*REAR INNER TAIL LIGHT - RH	Cracked	1,030.00 FS	*824.00 FS
11	1		*REAR INNER TAIL LIGHT TRIM - RH	Missing	34.00 FS	*26.48 FS
12	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	693.00 FS	*- FS
13	1		*REAR BUMPER SHOCK ABSORBER	Not Necessary	95.00 FS	*- FS
14	2		*REAR BUMPER HOLDING STRAP - LH / RH	Not Necessary	64.00 FS	*- FS
15	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	71.00 FS	*- FS
16	2		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	531.00 FS	*- FS
17	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
18	1		*SET REAR BUMPER WIRING	Cut	449.00 FS	*358.80 FS
19	1		*REAR UNDERBODY TRIM - RH	Not Necessary	58.00 FS	*- FS
20	1		*REAR LID	Dented	3,728.00 FS	*2,982.40 FS
21	1		*PACKING ADHESIVE	Necessary	21.00 FS	*16.80 FS
22	1		*REAR LID FLAP GASKET	Not Necessary	229.00 FS	*- FS
23	2		*REAR LID STOP BUFFER - LH / RH	Not Necessary	61.00 FS	*- FS
24	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
25	1		*Q3 INSCRIPTION	Necessary	104.00 FS	*82.80 FS
26	1		*REAR WINDSCREEN	Necessary	1,064.00 FS	*851.20 FS
27	1		*WINDSCREEN PRIMER	Necessary	22.00 FS	*17.36 FS
28	2		*REAR SPOILER - LH / RH	Necessary	470.00 FS	*375.20 FS
29	1		*REAR VENT TRIM	Not Necessary	79.00 FS	*- FS
30	2		*REAR WHEEL COVER - LH / RH	Necessary	1,132.00 FS	*904.80 FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
32	1		*SUNDRIES	Necessary	500.00 FS	*48.48 FS
33	1		*REAR END PANEL - OUTER (Supplementary)	Dented	445.00 FS	*355.60 FS
34	4		*REAR LID BUNG (Supplementary)	Necessary	133.00 FS	*105.92 FS
35	1		*ACRYLIC SEALER (Supplementary)	Necessary	180.00 FS	*180.00 FS
36	1		*CAVITY WAX (Supplementary)	Necessary	140.00 FS	*140.00 FS
37	1		*STONE CHIP (Supplementary)	Necessary	180.00 FS	*180.00 FS
38	1		*METAL FILLER POWDER (Supplementary)	Necessary	280.00 FS	*280.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)**    **15,851.00**    **10,887.68**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	480.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	400.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	150.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR RHS TAILLAMP PANEL AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
7	TO RESPRAY REAR BUMPER, REAR LID, RHS TAILLAMP PANEL, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS	New	4,500.00	2,050.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. (Supplementary)	New	1,600.00	1,600.00
10	TO CUT OUT AND WELD REAR END OUTER PANEL. TO REPAIR REAR END INNER PANEL AND REAR FENDER CONNECTING PLATE. (Supplementary)	New	2,400.00	1,500.00
<b>Gross Labour Cost (\$\$)</b>			<b>13,812.00</b>	<b>8,212.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >