

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010612/AVCE2**Date:** 02/03/2023**REFERENCE****Insured/Claimant:** TAN HEA HONG (CHEN HUOFENG)**Policy No:** 2100461226**Date of Loss:** 19/10/2022**Nature of Claim:** OD**Claim No:** 5439167530SG**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SGX9449X**Make & Model:** AUDI A4, 1.4 TFSI S TRONIC (A)**Engine No:** CVN006845**Reg. Date:** 25/04/2016 (Man. Year: 2016)**Chassis No:** WAUZZZF40GA049082**Colour:** White**Odometer:** 102434 km**Engine Capacity:** 1395 cc**Market Value/New Car Price:** S\$70,000.00**Sum Insured (S\$):** Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 225/60 R12**Rear Tyre Size:** 225/60 R12**Front Left Side:** Continental 6 mm**Rear Left Side:** Continental 6 mm**Front Right Side:** Continental 6 mm**Rear Right Side:** Continental 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,546.00	17,911.60	12,634.40	41.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,202.00	6,602.00	3,600.00	35.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	40,748.00	24,513.60	16,234.40	39.84
+ GST 8.00/8.00% (S\$)	3,259.84	1,961.09	1,298.75	39.84
Nett Amount (S\$)	44,007.84	26,474.69	17,533.15	39.84

INSPECTION**Date of Assignment:** 27/10/2022**Date Inspected:** 25/10/2022 **Inspected At:**

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 8.0 days**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Deformed	219.00 FS	*174.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	254.00 FS	*203.20 FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	72.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cut	2,019.00 FS	*1,615.20 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Distorted	409.00 FS	*326.80 FS
9	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	139.00 FS	*110.80 FS
11	1		*FRONT BUMPER GUIDE SECTION - RH	Distorted	41.00 FS	*32.24 FS
12	1		*FRONT BUMPER BRACKET - RH	Not Necessary	254.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Cracked	143.00 FS	*114.00 FS
14	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
15	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
16	1		*FRONT BUMPER BRACKET - RH	Damaged	154.00 FS	*122.80 FS
17	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
18	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
19	1		*HORN BRACKET - RH	Not Necessary	33.00 FS	*- FS
20	1		*FRONT FENDER - RH	Dented	861.00 FS	*688.80 FS
21	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	225.00 FS	*- FS
22	1		*FRONT FENDER CLOSING ELEMENT - RH	Damaged	81.00 FS	*64.24 FS
23	1		*FRONT FENDER BRACKET - RH	Bent	41.00 FS	*32.72 FS
24	1		*FRONT FENDER DEFORMATION BRACKET - RH	Not Necessary	55.00 FS	*- FS
25	7		*FRONT FENDER RIVET	Necessary	27.00 FS	*21.28 FS
26	1		*FRONT FENDER BRACE - RH	Bent	132.00 FS	*105.20 FS
27	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	262.00 FS	*209.60 FS
28	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
29	1		*FRONT WHEEL SPOILER - RH	Torn	82.00 FS	*65.60 FS
30	1		*FRONT WHEEL SPOILER END PLATE - RH	Damaged	40.00 FS	*32.00 FS
31	1		*FRONT STONE CHIP GUARD - RH	Not Necessary	57.00 FS	*- FS
32	1		*FRONT FENDER LEDGE COVER - RH OUTER	Cracked	35.00 FS	*27.52 FS
33	1		*FRONT FENDER LEDGE COVER - RH	Damaged	26.00 FS	*20.16 FS
34	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
35	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
36	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
37	1		*BONNET STRIKER	Not Necessary	56.00 FS	*- FS
38	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
39	1		*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
40	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
41	1		*HEADLIGHT - RH	Cut	8,294.00 FS	*6,635.20 FS
42	1		*HEADLIGHT POWER MODULE	Not Necessary	842.00 FS	*- FS
43	1		*HEADLIGHT CONTROL UNIT	Dented	840.00 FS	*672.00 FS
44	1		*HEADLIGHT HOSE	Not Necessary	42.00 FS	*- FS
45	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	45.00 FS	*- FS
46	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	47.00 FS	*- FS
47	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	45.00 FS	*- FS
48	1		*LIFT CYLINDER - RH	Cracked	231.00 FS	*184.40 FS
49	1		*LIFT CYLINDER BRACKET	Damaged	7.00 FS	*5.44 FS
50	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
51	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	45.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*LOCK CARRIER	Cracked	1,478.00 FS	*901.60 FS
53	1		*RADIATOR SUPPORT BRACKET	Not Necessary	43.00 FS	*- FS
54	1		*RADIATOR - LOWER CENTRE	Not Necessary	545.00 FS	*- FS
55	1		*RADIATOR COOLANT	Not Necessary	699.00 FS	*- FS
56	1		*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
57	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
58	6		*READY-MIX COOLANT	Necessary	297.00 FS	*237.12 FS
59	1		*RADIATOR AIR GUIDE - RH INNER	Not Necessary	32.00 FS	*- FS
60	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Not Necessary	28.00 FS	*- FS
61	1		*RADIATOR AIR GUIDE - UPPER CENTER	Not Necessary	19.00 FS	*- FS
62	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
63	1		*INTAKE AIR DUCT - RH LOWER	Not Necessary	25.00 FS	*- FS
64	1		*INTAKE AIR DUCT - CENTER	Not Necessary	61.00 FS	*- FS
65	1		*INTAKE HOSE	Not Necessary	110.00 FS	*- FS
66	1		*AIR FILTER	Not Necessary	418.00 FS	*- FS
67	1		*NOISE INSULATION	Deformed	640.00 FS	*512.00 FS
68	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
69	1		*SUNDRIES	Necessary	500.00 FS	*3.04 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	30,546.00	17,911.60
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	2,750.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	3,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			10,202.00	6,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >