

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010617/ENCE2**Date:** 05/06/2023**REFERENCE**

Insured/Claimant:	GOH LAI PENG	Policy No:	7220055887	
Date of Loss:	23/10/2022	Nature of Claim:	OD	Claim No: 4872603261SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA782E		
Make & Model:	AUDI Q2, 1.5 TFSI S TRONIC (A)	Engine No:	DPCD88228
Reg. Date:	25/05/2022 (Man. Year: 2021)	Chassis No:	WAUZZZGA0NA011224
Colour:	Grey	Odometer:	3888 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$167,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,214.00	15,114.08	9,099.92	37.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,732.00	10,182.00	10,550.00	50.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,946.00	25,296.08	19,649.92	43.72
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	44,146.00	24,496.08	19,649.92	44.51
+ GST 8.00/8.00% (S\$)	3,531.68	1,959.69	1,571.99	44.51
Nett Amount (S\$)	47,677.68	26,455.77	21,221.91	44.51

INSPECTION

Date of Assignment:	27/10/2022	
Date Inspected:	26/10/2022	Inspected At: 24 Benoi Sector Singapore 629857 Premium Automobiles Pte Ltd
Estimated Period of Repair:	11.0 days	

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,390.00 FS	*1,112.00 FS
2	1		*FRONT BUMPER BRACKET - LH / RH	O/S Broken	27.00 FS	*10.48 FS
3	1		*FRONT BUMPER ADAPTER - RH	Broken	48.00 FS	*37.76 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Broken	220.00 FS	*175.60 FS
5	1		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	O/S Missing	66.00 FS	*25.68 FS
6	1		*FRONT BUMPER TRIM - RH	Missing	104.00 FS	*83.20 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Broken	101.00 FS	*80.80 FS
8	1		*FRONT PARKING AID SENSOR SUPPORT - RH	Necessary	33.00 FS	*25.68 FS
9	1		*FRONT BUMPER GRILLE COVER - LOWER CENTER	Not Necessary	18.00 FS	*- FS
10	1		*FRONT BUMPER LOWER TRIM	Broken	113.00 FS	*90.40 FS
11	1		*FRONT BUMPER CLOSING ELEMENT	Broken	174.00 FS	*138.80 FS
12	1		*FRONT WHEEL SPOILER - RH	Cut	38.00 FS	*30.24 FS
13	1		*FRONT BUMPER SPOILER	Broken	332.00 FS	*265.60 FS
14	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	48.00 FS	*- FS
15	1		*RADIATOR GRILLE	Broken	1,561.00 FS	*1,248.80 FS
16	1		*RADIATOR GRILLE STRIKER PLATE	Broken	212.00 FS	*169.20 FS
17	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	87.00 FS	*- FS
18	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	769.00 FS	*614.80 FS
19	1		*FRONT BUMPER GUIDE SECTION - RH	Broken	40.00 FS	*31.84 FS
20	1		*FRONT BUMPER TOP COVER	Broken	112.00 FS	*89.60 FS
21	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
22	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
23	1		*ENGINE OIL STICKER	Not Necessary	13.00 FS	*- FS
24	1		*HORN HIGH TONE - RH	Broken	162.00 FS	*129.20 FS
25	1		*HORN BRACKET - RH	Not Necessary	35.00 FS	*- FS
26	1		*FRONT FENDER - RH	Dented	1,285.00 FS	*1,028.00 FS
27	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	42.00 FS	*- FS
28	1		*FRONT FENDER BRACKET - RH FRONT	Bent	56.00 FS	*44.40 FS
29	1		*FRONT FENDER BRACKET - RH CENTER	Bent	18.00 FS	*13.92 FS
30	1		*FRONT FENDER BRACKET - RH REAR	Bent	18.00 FS	*13.92 FS
31	1		*FRONT FENDER RIVET (7PCS)	Necessary	27.00 FS	*21.28 FS
32	1		*FRONT FENDER BRACKET FOR HEADLIGHTS	Not Necessary	26.00 FS	*- FS
33	1		*FRONT FENDER BRACE - RH	Bent	59.00 FS	*46.56 FS
34	1		*FRONT FENDER INSULATION - RH	Not Necessary	85.00 FS	*- FS
35	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	37.00 FS	*- FS
36	1		*FRONT WHEEL HOUSING LINER - RH	Broken	213.00 FS	*170.00 FS
37	1		*HEADLIGHT MOUNTING - RH	Broken	132.00 FS	*105.20 FS
38	1		*HEADLIGHT - RH	Broken	6,147.00 FS	*4,917.60 FS
39	1		*HEADLIGHT HOSE - RH	Not Necessary	34.00 FS	*- FS
40	1		*HEADLIGHT COMPESATING PIECE	Missing	53.00 FS	*42.00 FS
41	1		*LIFT CYLINDER - RH	Broken	156.00 FS	*124.40 FS
42	1		*LIFT CYLINDER HOSE	Torn	89.00 FS	*70.48 FS
43	1		*LOCK CARRIER	Broken	1,101.00 FS	*880.80 FS
44	1		*A/C CONDENSER	Not Necessary	605.00 FS	*- FS
45	1		*A/C CONDENSER REFRIGERANT LINE	Bent	623.00 FS	*498.40 FS
46	1		*A/C CONDENSER REFRIGERANT LINE	Bent	500.00 FS	*400.00 FS
47	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	570.00 FS	*- FS
48	1		*RADIATOR	Not Necessary	1,064.00 FS	*- FS
49	1		*ADDITIONAL RADIATOR	Broken	961.00 FS	*768.80 FS
50	2		*RADIATOR BRACKET - UPPER	Necessary	90.00 FS	*71.84 FS
51	2		*RADIATOR BUSH - LOWER	Necessary	22.00 FS	*16.96 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*RADIATOR AIR GUIDE - RH	Not Necessary	35.00 FS	*- FS
53	6		*READY-MIX COOLANT	Necessary	297.00 FS	*237.12 FS
54	1		*RADIATOR AIR GUIDE - RH	Broken	43.00 FS	*34.08 FS
55	1		*RADIATOR AIR GUIDE SEAL - RH OUTER	Not Necessary	8.00 FS	*- FS
56	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	32.00 FS	*- FS
57	1		*AIR INTAKE UPPER COVER	Not Necessary	30.00 FS	*- FS
58	1		*AIR INTAKE AIR GUIDE - LOWER	Not Necessary	59.00 FS	*- FS
59	1		*AIR INTAKE AIR GUIDE - CENTER	Not Necessary	36.00 FS	*- FS
60	1		*AIR INTAKE AIR GUIDE - REAR	Not Necessary	36.00 FS	*- FS
61	1		*AIR FILTER	Not Necessary	337.00 FS	*- FS
62	1		*RADIATOR WATER DRAINAGE HOSE	Not Necessary	37.00 FS	*- FS
63	2		*FRONT WHEEL COVER - LH / RH	Necessary	720.00 FS	*576.00 FS
64	1		*FRONT WINDSCREEN APERTURE SEAL - RH OUYER	Not Necessary	151.00 FS	*- FS
65	1		*FRONT WINDSCREEN GUIDE - RH	Not Necessary	459.00 FS	*- FS
66	1		*FRONT DOOR COVER - RH	Cut	270.00 FS	*216.00 FS
67	1		*FRONT DOOR COVER PLATE - RH	Not Necessary	107.00 FS	*- FS
68	1		*FRONT ALUMINIUM RIM	Not Necessary	899.00 FS	*- FS
69	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
70	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
71	1		*SUNDRIES	Necessary	500.00 FS	*95.60 FS
72	1		*FRONT NOISE INSULATION	Broken	353.00 FS	*282.00 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	24,214.00	15,114.08
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,600.00	1,600.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO RENEW RHS FRONT FENDER INNER AIRCON PIPE	New	280.00	0.00
6	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
7	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT, BONNET, RHS UPPER A-PILLAR AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS FRONT CHASSIS FRAME COVER PLATE. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	8,000.00	2,750.00
8	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT FENDER TOP SUPPORT, RHS FRONT CHASSIS FRAME COVER PLATE, RHS UPPER A-PILLAR AND RHS FRONT DOOR	New	5,500.00	2,750.00
9	TO RENEW RHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	0.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
11	TO REPAIR RHS FRONT WHEEL HOUSING (Supplementary)	New	1,200.00	250.00
12	TO RESPRAY RHS FRONT WHEEL HOUSING (Supplementary)	New	1,200.00	550.00
Gross Labour Cost (\$\$)			20,732.00	10,182.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >